

Equipment Record Report #6592512

Date: 2024-03-22

Unit Code	Machine	Type	Operator	Downtime	Area	Comments
MC-210	Paint Booth	Preventive	Laura Rossi	2.6	Plant 1C	Replaced coolant.
MC-283	Assembly Robot	Inspection	Carlos Garcia	3.4	Plant 2B	Replaced fuse (5A).
MC-268	Packaging Line	Preventive	Peter Schmidt	3.8	Plant 3A	No issues found.
MC-269	Packaging Line	Preventive	Carlos Garcia	3.4	Plant 3A	Worn gasket replaced.
MC-247	Lathe	Corrective	Carlos Garcia	2.9	Plant 3A	Refilled oil (HLP 46).
MC-224	Conveyor Belt	Corrective	Jan Kowalski	2.5	Plant 2B	Worn gasket replaced.
MC-255	Assembly Robot	Corrective	Jan Kowalski	3.4	Plant 2B	Worn gasket replaced.
MC-242	CNC Milling Machine	Corrective	Carlos Garcia	2.5	Plant 3A	Wooden pallet checked.
MC-214	Laser Cutter	Inspection	Carlos Garcia	1.8	Plant 2B	Calibration check OK.
MC-263	Lathe	Corrective	Laura Rossi	1.7	Plant 1C	Replaced fuse (5A).

All maintenance durations are recorded for performance metrics. Check remaining life-cycles of key components from this report. Refer to remarks for any follow-up actions or parts replacements. Service summaries have been forwarded to the engineering team.

Lubrication Checked	No
Calibration Verified	No
Emergency Stop Tested	N/A

Authorized by: \_\_\_\_\_ Operator: \_\_\_\_\_