

| Machine ID | Equipment | Type | Operator | Duration | Site | Notes |
|------------|-----------------|------------|---------------|----------|----------|-------------------------------|
| MC-295 | Conveyor Belt | Corrective | Anna Nowak | 3.0 | Plant 1C | Sensor recalibrated. |
| MC-267 | Conveyor Belt | Corrective | Laura Rossi | 3.4 | Plant 2B | Alignment of hinges adjusted. |
| MC-201 | Assembly Robot | Preventive | Jan Kowalski | 2.3 | Plant 1C | Switch contacts cleaned. |
| MC-210 | Hydraulic Press | Inspection | Anna Nowak | 3.8 | Plant 2B | Refilled oil (HLP 46). |
| MC-202 | Lathe | Corrective | Laura Rossi | 1.9 | Plant 3A | Switch contacts cleaned. |
| MC-275 | Laser Cutter | Inspection | Carlos Garcia | 3.9 | Plant 3A | Changed oil and filters. |
| MC-238 | Laser Cutter | Inspection | Jan Kowalski | 1.7 | Plant 2B | Replaced fuse (5A). |
| MC-226 | Conveyor Belt | Inspection | Jan Kowalski | 3.7 | Plant 3A | No issues found. |
| MC-241 | Conveyor Belt | Inspection | Laura Rossi | 2.9 | Plant 1C | Changed oil and filters. |

Service summaries have been forwarded to the engineering team. Confirm that all corrective actions were properly closed out. This log summary supports the asset-management dashboard. Check remaining life-cycles of key components from this report.

| | |
|-----------------------|-----|
| Lubrication Checked | N/A |
| Calibration Verified | N/A |
| Emergency Stop Tested | No |

Signed off: _____ Performed by: _____