

## Maintenance Checklist Report

Performed On: 2024-07-07

|              |             |
|--------------|-------------|
| Approved by: | Anna Nowak  |
| Serviced by: | Laura Rossi |

Use this record to plan upcoming upkeep and repairs. This log records all maintenance activities performed on the equipment. Use this summary to forecast parts replacement and resource needs. This section captures equipment status and any maintenance observations. This service summary supports the reliability engineering review. Ensure all safety checks were completed during servicing. Please review this log for recent service dates, types, and remarks.

Section A:

|            |                      |                      |                               |                               |
|------------|----------------------|----------------------|-------------------------------|-------------------------------|
| Machine ID | MC-281               | MC-240               | MC-246                        | MC-217                        |
| Machine    | Packaging Line       | Lathe                | Plasma Cutter                 | Paint Booth                   |
| Type       | Corrective           | Preventive           | Corrective                    | Corrective                    |
| Technician | Laura Rossi          | Anna Nowak           | Carlos Garcia                 | Peter Schmidt                 |
| Downtime   | 3.6                  | 3.8                  | 2.6                           | 3.6                           |
| Notes      | Sensor recalibrated. | Sensor recalibrated. | Li-Ion battery pack serviced. | Li-Ion battery pack serviced. |

Section B:

|            |                       |             |                     |                        |
|------------|-----------------------|-------------|---------------------|------------------------|
| Machine ID | MC-246                | MC-217      | MC-240              | MC-281                 |
| Machine    | Plasma Cutter         | Paint Booth | Lathe               | Packaging Line         |
| Type       | Inspection            | Corrective  | Inspection          | Preventive             |
| Technician | Carlos Garcia         | Laura Rossi | Carlos Garcia       | Carlos Garcia          |
| Downtime   | 3.3                   | 3.8         | 2.1                 | 3.2                    |
| Notes      | Calibration check OK. |             | Replaced fuse (5A). | Wooden pallet checked. |

|            |             |       |
|------------|-------------|-------|
| Uptime (%) | Error Count | Notes |
| 98.70%     | 5           |       |