

**Maintenance Checklist Report #7982122**

---

Date: 2025-04-04

Machine ID	Machine	Service Type	Technician	Downtime	Area	Comments
MC-238	Hydraulic Press	Inspection	Laura Rossi	3.9	Plant 3A	Refilled oil (HLP 46).
MC-256	Paint Booth	Preventive	Carlos Garcia	3.2	Plant 3A	No issues found.
MC-252	Paint Booth	Preventive	Jan Kowalski	3.8	Plant 1C	
MC-289	Paint Booth	Corrective	Anna Nowak	2.8	Plant 1C	Changed oil and filters.
MC-213	Laser Cutter	Corrective	Laura Rossi	3.3	Plant 2B	Tightened loose bolts.
MC-229	Plasma Cutter	Inspection	Laura Rossi	2.0	Plant 3A	Tightened loose bolts.
MC-277	Assembly Robot	Inspection	Anna Nowak	1.6	Plant 2B	Sensor recalibrated.
MC-272	Paint Booth	Preventive	Laura Rossi	3.2	Plant 1C	No issues found.
MC-270	Hydraulic Press	Inspection	Carlos Garcia	3.3	Plant 2B	Wooden pallet checked.

Service summaries have been forwarded to the engineering team. All maintenance durations are recorded for performance metrics. Check remaining life-cycles of key components from this report. Flag any recurring issues for root-cause investigation.

Lubrication Checked	N/A
Calibration Verified	N/A
Emergency Stop Tested	N/A

Authorized by: \_\_\_\_\_ Operator: \_\_\_\_\_