

# Equipment Record Report

Performed On: 2023-11-05

Approved by:	Peter Schmidt
Serviced by:	Anna Nowak

Below is the summary of service actions and downtimes for each machine. Please review this log for recent service dates, types, and remarks. All technician comments are recorded for maintenance trend analysis. Use this summary to forecast parts replacement and resource needs. This service summary supports the reliability engineering review.

Section A:

Machine ID	MC-296	MC-209	MC-223	MC-230	MC-235
Equipment	Hydraulic Press	Packaging Line	Laser Cutter	Laser Cutter	CNC Milling Machine
Service Type	Preventive	Corrective	Corrective	Inspection	Corrective
Technician	Jan Kowalski	Peter Schmidt	Peter Schmidt	Carlos Garcia	Laura Rossi
Duration	3.6	3.7	1.5	2.4	3.5
Comments	Tightened loose bolts.	Refilled oil (HLP 46).	Replaced fuse (5A).	Tightened loose bolts.	Switch contacts cleaned.

Section B:

Machine ID	MC-230	MC-209	MC-235	MC-223	MC-296
Equipment	Laser Cutter	Packaging Line	CNC Milling Machine	Laser Cutter	Hydraulic Press
Service Type	Inspection	Corrective	Inspection	Preventive	Inspection
Technician	Anna Nowak	Carlos Garcia	Laura Rossi	Carlos Garcia	Laura Rossi
Duration	2.5	2.9	3.5	3.6	2.9
Comments	Replaced fuse (5A).		Worn gasket replaced.	Replaced coolant.	Replaced fuse (5A).

Uptime (%)	Error Count	Notes
98.16%	0	Bolt tightened