



*Taking Control . . . To A Higher Level*

Price \$5.00

## PRO II X Series CAPACITANCE PROBE



**OPERATING INSTRUCTIONS**  
**PLEASE READ CAREFULLY**



Division of Garner Industries  
7201 No. 98th Street P. O. Box 29709  
Lincoln, NE 68507 Lincoln, NE 68529  
(402) 434-9102 Fax (402) 434-9133  
[www.binmaster.com](http://www.binmaster.com)

# TABLE OF CONTENTS

GENERAL SPECIFICATIONS .....	3
1.0 INTRODUCTION .....	4
2.0 APPLICATIONS .....	4
3.0 INSTALLATION .....	4
3.1 Location and Mounting .....	4
3.2 Input Power and Field Wiring .....	5
3.3 Grounding .....	5
4.0 FAIL-SAFE SELECTION .....	6
4.1 Description .....	6
4.2 Fail-Safe High .....	6
4.3 Fail-Safe Low .....	6
5.0 CALIBRATION .....	7
5.1 Calibration Verification .....	7
5.2 Calibration Procedure .....	7
5.3 Sensitivity Selection .....	7
6.0 TIME DELAY .....	8
7.0 WARRANTY AND CUSTOMER SERVICE .....	8
FIGURE 1.1 .....	9
FIGURE 1.2 .....	10
FIGURE 1.3 .....	11
FIGURE 1.4 .....	12
FIGURE 2.1 .....	13



## PRO II X GENERAL SPECIFICATIONS

<b>Supply:</b>	120/240 VAC 50/60 Hz
<b>Supply Tolerance:</b>	-15% +10%
<b>Load:</b>	5VA
<b>Ambient Temperature: (Electronics)</b>	-40° F to +185° F (-40° C to +85° C)
<b>Sensitivity:</b>	1 picofarad
<b>Enclosure:</b>	Type 4X, 5, 9 and 12
<b>Relay Output:</b>	DPDT contacts; 10 Amps 250 VAC
<b>Fail-Safe:</b>	Switch selectable "High" or "Low" level modes.
<b>Calibration:</b>	Set when probe is uncovered: COURSE adjust; single turn potentiometer FINE adjust; single turn potentiometer
<b>Status Indicator:</b>	Internal LED indicates material in contact with probe.
<b>Time Delay:</b>	Adjustable up to 10 seconds
<b>Probe Shield:</b>	Automatically compensates for material buildup on the probe
<b>Conduit Entry:</b>	3/4" NPT

## 1.0 INTRODUCTION

The Bin-Master PRO II X is a point level control used to detect the presence or absence of solids or liquids. The PRO II X operates on the capacitance principle and incorporates a "Quick Set" feature to simplify calibration. The PRO II X includes switch selectable Fail-Safe output contacts and "Probe Shield" technology for ignoring material build up.

Upon installation the PRO II X is set up with the probe uncovered. The "Quick Set" feature allows simple setup and calibration of the unit to achieve low, medium, or high sensitivity settings. The PRO II X has an adjustable time delay for monitoring covered or uncovered conditions.

## 2.0 APPLICATIONS

For applications in pressurized vessels up to 500 PSI, the PRO II X should be mounted with the 3/4" stainless steel coupling.

Application temperatures for the various probes are:

1. Delrin Sleeved Stainless Steel:	250 Deg. F
2. Teflon Sleeved Stainless Steel:	500 Deg. F
3. Flush Mount (Polyethylene):	180 Deg. F
4. Flush Mount (Teflon):	450 Deg. F
5. Bare Stainless Steel:	250 Deg. F
6. Flexible Extension:	250 Deg. F

The Delrin or Teflon sleeved stainless steel probe should be used when mounting the PRO II X in a highly corrosive atmosphere. Bare metal Stainless Steel probes are suitable for granular or liquid material that is not electrically conductive. For electrically conductive material, a coated (insulated) probe must be used.

## 3.0 INSTALLATION

### 3.1 Location and Mounting

The probe should be located out of the direct flow of material. The PRO II X is designed to mount utilizing either a 1 1/4" NPT coupling or 3/4" NPT coupling. When the PRO II X is used with the flush mount probe, the flush mount probe mounts directly to the vessel wall using a 7" diameter bolt circle. Refer to Figures 1.1 through 1.4 for illustrations on installation, mounting options, and different probe combinations.

## 3.2 Input Power and Field Wiring

The PRO II X can be powered from either a 120 VAC or 240 VAC supply (see diagram below). Field wiring should conform to all national and local electrical codes and any other agency or authority having jurisdiction over the installation.



## 3.3 Grounding

An equipment grounding connection (earth ground) **must** be supplied to the unit for safety and to insure proper operation of the unit. This unit uses earth ground as a reference for calibration and detecting a covered or uncovered condition. Therefore, the vessel in which the PRO II X is mounted must be made of metal, or a suitable metal ground plate must be installed where the PRO II X is mounted.

## 4.0 FAIL-SAFE SELECTION


### 4.1 Description

A Fail-Safe condition means that the relay contact positions are set up so that in the event of a power failure the relay will be de-energized and the contacts will indicate a condition that is deemed safe for the application. (Refer to FIGURE 2.1 for the location of the Fail-Safe selection switch.)

### 4.2 Fail-Safe High

Fail-Safe High means that the relay will be energized when the probe is uncovered and will de-energize when the probe is covered. In this mode, a power failure will cause the relay contacts to indicate that the probe is covered whether it is or not.

#### FAIL-SAFE HIGH RELAY CONTACT POSITION



### 4.3 Fail-Safe Low

Fail-Safe Low means that the relay will be de-energized when the probe is uncovered and will energize when the probe is covered. In this mode, a power failure will cause the relay contacts to indicate that the probe is uncovered whether it is or not.

#### FAIL-SAFE LOW RELAY CONTACT POSITION



## 5.0 CALIBRATION

The PRO II X Quick Set calibration uses two single turn potentiometers making calibration very simple. One potentiometer labeled COARSE is used to compensate for the capacitance of the empty vessel. The other potentiometer labeled FINE is used to set in the desired sensitivity. Refer to FIGURE 2.1 for the location of these potentiometers on the printed circuit board. A tool for adjusting the COARSE and FINE potentiometers is provided inside the top cover of the PRO II X. The cover has a convenient clip for storing the tool so it will always be available.

**NOTE:** Accurate calibration requires that the appropriate probe is attached to the PRO II X and the unit installed in the vessel. The probe must be UNCOVERED and material well below it.

### 5.1 Calibration Verification

Following calibration adjustment, the sensitivity setting that you have selected should be checked by verifying that the PRO II X senses a covered probe condition with your material.

### 5.2 Calibration Procedure

1. Turn both the COARSE and FINE potentiometers fully counter clockwise (CCW). The internal COVERED indicator light should be OFF.
2. Turn the COARSE potentiometer slowly clockwise (CW) to the point where the COVERED indicator light just turns ON and stays on.
3. Turn the FINE potentiometer slowly clockwise (CW) until the COVERED indicator light just turns OFF. (If the COARSE potentiometer has been carefully adjusted, this should occur when the FINE potentiometer is between the 8 and 10 O'clock position.) Now continue to turn the FINE potentiometer clockwise (CW) to the desired sensitivity setting.

HIGH sensitivity:	1/16 to 1/8 turn (1 to 3 picofarad)
MEDIUM sensitivity:	1/8 to 1/4 turn (3 to 6 picofarad)
LOW sensitivity:	1/4 to 1/2 turn (6 to 12 picofarad)

**NOTE:** It may be convenient to think of the FINE potentiometer as a clock face where the distance between consecutive hour numbers represent a change in sensitivity of approximately 2 picofarad. Thus turning the FINE potentiometer clockwise one hour position past the point at which the COVERED indicator just turns OFF would provide a sensitivity of approximately 2 picofarad. Two-hour positions past that point would provide approximately 4 picofarad sensitivity, etc.

### 5.3 Sensitivity Selection

Sensitivity Setting (typical)	Dielectric Constant of Material
HIGH sensitivity:	4 or less
MEDIUM sensitivity:	4 to 10
LOW sensitivity:	10 or higher

## **6.0 TIME DELAY**

The PRO II X has an adjustable time delay of up to 10 seconds. This is a time delay for the output to change states from an uncovered to a covered condition and from a covered to an uncovered condition. This time delay affects the relay contacts only. The internal LED (DS1) will immediately respond to a change in covered or uncovered condition regardless of the time delay setting.

Minimum time delay is when the DELAY potentiometer is set fully counter-clockwise. (Refer to FIGURE 2.1 for the location of the DELAY potentiometer.) Maximum time delay is with the DELAY potentiometer set fully clockwise.

A tool for adjusting the TIME DELAY potentiometer is provided inside the top cover of the PRO II X. The cover has a convenient clip for storing the tool so it will always be available.

## **7.0 WARRANTY AND CUSTOMER SERVICE**

### **7.1 Limited Warranty**

The manufacturer warrants this equipment for two (2) years according to the following terms:

- 1.) This warranty extends to the original purchaser only and commences on the date of original purchase. The original purchaser must mail to the manufacturer the "Warranty Registration" card to confirm the equipment purchase. Failure to do so may void the warranty.
- 2.) The manufacturer will repair or replace any part of this equipment found to be defective, provided such part is delivered prepaid, to the factory. Manufacturer's obligation is limited to the cost of material and labor to repair or replace and does not include transportation expenses.
- 3.) This warranty shall not apply to any product that has, in our judgment, been tampered with, altered, subject to misuse, neglect or accident. In addition, the warranty does not extend to repairs made necessary by normal wear.
- 4.) This warranty is in lieu of all other warranties, expressed or implied.

### **7.2 Custom Service**

Bin Master offers a toll-free Customer Service phone number **1-800-278-4241**. You may call the Customer Service Department for technical and application assistance Monday through Friday from 8:00AM to 5:00 PM Central Time. International customers call us at **(402) 434-9102** or reach us via **fax** at **(402) 434-9133**.








Figure 1.1



## Flush Mount Probe

Figure 1.2

9270061.dgn  
927b061.tif



**Figure 1.3**




Figure 1.4






Figure 2.1

# Mounting Instructions



Always Mount Unit with Conduit  
Opening Down



## CONDUIT SEAL

When installing this level indicator in environments where it is possible for moisture or moist air to enter the enclosure thru the electrical conduit, the conduit opening should be sealed with a duct seal compound or putty appropriate for the purpose.

# **BINMASTER**

Division of Garner Industries  
7201 No. 98th Street P. O. Box 29709  
Lincoln, NE 68507 Lincoln, NE 68529  
(402) 434-9102 Fax (402) 434-9133  
[www.binmaster.com](http://www.binmaster.com)