



1. Draw center line and cross sections identifying shape transitions



2. Connect cross sections to create outer profile



3. Offset outer profile and add bottom details to express clear glass



4. Add contour lines, bubbles and thick stroke on perimeter/ part breaks

