




1. Solder the header first, laying flat on a table.
2. Solder the chip in next.  
Make sure you align the dip on the front side of the chip.
3. Solder the resistors
4. Solder the USB jack.  
Add solder to the pads first, keeping the power pins in line with the traces on board.




1. Solder the header first, laying flat on a table.
2. Solder the chip in next.  
Make sure you align the dip on the front side of the chip.
3. Solder the resistors
4. Solder the USB jack.  
Add solder to the pads first, keeping the power pins in line with the traces on board.




1. Solder the header first, laying flat on a table.
2. Solder the chip in next.  
Make sure you align the dip on the front side of the chip.
3. Solder the resistors
4. Solder the USB jack.  
Add solder to the pads first, keeping the power pins in line with the traces on board.



1. Solder the header first, laying flat on a table.
2. Solder the chip in next.  
Make sure you align the dip on the front side of the chip.
3. Solder the resistors
4. Solder the USB jack.  
Add solder to the pads first, keeping the power pins in line with the traces on board.



1. Solder the header first, laying flat on a table.
2. Solder the chip in next.  
Make sure you align the dip on the front side of the chip.
3. Solder the resistors
4. Solder the USB jack.  
Add solder to the pads first, keeping the power pins in line with the traces on board.



1. Solder the header first, laying flat on a table.
2. Solder the chip in next.  
Make sure you align the dip on the front side of the chip.
3. Solder the resistors
4. Solder the USB jack.  
Add solder to the pads first, keeping the power pins in line with the traces on board.