




WORK INSTRUCTION TAPING ASSEMBLY PROCESS

Effectivity Date:	January 06, 2022		
Validity Date:	n/a		
Document No.:	WI-ENG-PDE-339B		
Revision No.:	1	Page No.:	1 of 7

Process Name/Title:	TAPING ASSEMBLY PROCESS		
Model Code/Part Number:	178D / 7N0129-7020	Customer:	TRJ
Purpose:	<input type="checkbox"/> PROTOTYPE <input type="checkbox"/> PRE-LAUNCH <input checked="" type="checkbox"/> MASSPRO		

PARTS: 1. Assy parts; Black tape [1pc]

JIG: 1. Insertion jig
2. Locking jig
3. Terminal cover jig

NO.	PROCESS NAME	WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS
1	P2 1 Table Lay-out	<p>Table Lay-out</p> 	<p>Safety Instruction Be sure to wear required personal protective equipment during operation (gloves, finger cots, etc.)</p> <p>Housekeeping 1. Maintain and always practice 5's. 2. Personal things on the workplace is prohibited. Keep it in your locker.</p> <p>Alert level For any trouble, inform the Assembly Assistant Supervisor or Line Leader for immediate corrective action.</p>	1. No missing parts/tools 2. No excess parts/tools

Revision History

Eff. Date	Rev. No	Details of Change	Revised	Reviewed	Approved	Noted	Prepared by	Reviewed by	Approved by	Noted by
01/06/22	1	Change from Pre-launch to Masspro. Improve work procedure/illustration and quality pointers; Additional Table Lay-out.	M. Catapang	J. Loterte	C. Villanueva	A. Arañes	M. Catapang	J. Loterte	C. Villanueva	A. Arañes
09/20/21	0	Initial issue	M. Catapang	J. Loterte	C. Villanueva	A. Arañes	M. Catapang	J. Loterte	C. Villanueva	A. Arañes

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp

**WORK INSTRUCTION**

Process Name/Title:

TAPING ASSEMBLY PROPCESS

Effectivity Date:

January 06, 2022

Model Code/Part Number:

178D / 7N0129-7020

Customer:

TRJ

Validity Date:

n/a

Document No.:

WI-ENG-PDE-339B

Purpose:








☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

2 of 7

PARTS:		1. Assy parts		JIG	1. Terminal cover jig 2. Insertion jig
NO.	PROCESS NAME	1 WORK PROCEDURE/ ILLUSTRATION		TOOLS/PPE	QUALITY POINTERS
2	Wire insertion to assy part 1	<div><div><p>1. Get the MRSW CP GR-B/W wires L=822±3mm using both hands then insert the terminal cover jig using right hand.</p></div><div><p>COT Ø7 L=214±3mm</p><p>2. Get the assy parts then hold the COT (no slit) Ø7 L=214±3mm using left hand then insert the MRSW CP GR-B/W wires L=822±3mm using right hand.</p></div><div><p>3. After insertion, remove the cover jig using right hand.</p></div></div>		<div><p>TERMINAL COVER JIG</p></div>	1. No wrong usage of parts 2. No damaged rubber seal 3. No exposed rubber seal during insertion
3	Connector setting to insertion jig 6188-0066 (GR) (Assy parts)	<div><div><p>Visual reference</p><p>Wire guide</p><p>Push button</p></div><div><p>I-mark</p><p>Lock</p><p>INSERTION JG ORIENTATION</p></div><div><p>CONNECTOR ORIENTATION</p></div></div>		n/a	1. Use the provided jig per model 2. No wrong orientation of connector 3. No wrong use of connector 4. No damaged connector

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

Process Name/Title:

TAPING ASSEMBLY PROPCESS

Effectivity Date:

January 06, 2022

Model Code/Part Number:

178D / 7N0129-7020

Customer:

TRJ

Validity Date:

n/a

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Document No.:







WI-ENG-PDE-339B

Revision No.:

1

Page No.:

3 of 7

PARTS:		1. Assy parts		JIG	1. Insertion jig
NO.	PROCESS NAME	1 WORK PROCEDURE/ ILLUSTRATION	TOOLS/PPE	QUALITY POINTERS	
3	P2 Connector setting to insertion jig 6188-0066 (GR) (Assy parts) (Continuation)	<div><div><p>Hole</p><p>1. Push the lower wire guide upward using right thumb. Slot for Gray wire will be opened.</p></div><div><p>Press</p><p>2. Press the lock using left thumb.</p></div><div><p>Press</p><p>Release</p><p>3. Get the connector 6188-0066 (GR) using right hand and insert to insertion jig. Release the lock after insertion. <i>Note: Follow the connector orientation.</i></p></div></div>	n/a	<div><div><p>I-mark is align</p><p>1 hole is open</p><p>GOOD</p></div><div><p>I-mark is not align</p><p>2 holes are open</p><p>NG</p></div></div> <p>1. Use the provided jig per model 2. No wrong orientation of connector 3. No wrong use of connector 4. No damaged connector</p>	

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Effectivity Date:

January 06, 2022

Process Name/Title:

Validity Date:

n/a

Model Code/Part Number: 178D / 7N0129-7020

Customer: TRJ

Document No.:

WI-ENG-PDE-339B

Purpose: ☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

5 of 7

PARTS:

1. Assy parts
2. Black tape

JIG

n/a

NO.

PROCESS NAME

WORK PROCEDURE/ ILLUSTRATION


TOOLS/PPE

QUALITY POINTERS

6


n/a

Taping 1
Black corrugated tube to
wire near connector




1. Hold the corrugated tube using left hand then start taping using right hand.

2. Confirm **25±3mm** measurement from end of tape up to end of corrugated tube then continue the taping process using both hands.



3. Measure from end corrugated tube up to edge of connector **25±3mm** then continue the taping process using both hands.



3. After taping, check the measurement and taping condition.

MEASURING TAPE



1. No flip-out tape
2. No peel-off tape
3. No loose tape
4. No missing tape
5. No wrong dimension
6. No wrong use of tape

Note:

Please use calibrated/verified measuring tape when getting the measurement.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Effectivity Date:

January 06, 2022

Process Name/Title:

Model Code/Part Number: 178D / 7N0129-7020

Customer: TRJ

Validity Date:

n/a

Document No.:

WI-ENG-PDE-339B

Purpose:

☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Revision No.:

1

Page No.:

6 of 7

PARTS:

1. Assy parts
2. Black tape

JIG

n/a

NO.

PROCESS NAME

WORK PROCEDURE/ ILLUSTRATION


TOOLS/PPE

QUALITY POINTERS

7

n/a

Y-Taping



tape shifting 1/3 below

taping direction

30±3mm

MEASURING TAPE

1. No flip-out tape
2. No peel-off tape
3. No loose tape
4. No missing tape
5. No wrong dimension
6. No wrong use of tape

Note:

Please use calibrated/verified measuring tape when getting the measurement.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp



WORK INSTRUCTION

TAPING ASSEMBLY PROCESS

Effectivity Date:

January 06, 2022

Process Name/Title:

Validity Date:

n/a

Model Code/Part Number: 178D / 7N0129-7020

Customer: TRJ

Document No.:

WI-ENG-PDE-339B

Purpose: ☐ PROTOTYPE☐ PRE-LAUNCH☒ MASSPRO

Revision No.:

1

Page No.:

7 of 7

PARTS:

1. Assy parts
2. Black tape

JIG

n/a

NO.

PROCESS NAME


WORK PROCEDURE/ ILLUSTRATION

TOOLS/PPE


QUALITY POINTERS

8


n/a

Y-Taping
(Continuation)


4. Wind the tape **1/3 shifting** until it reach the other side of corrugated tube (must be tape width).



5. Make **2 windings** of tape then wind **1/2 shifting** going to other side.



6. Make **2 windings** of tape then wind the tape **1/2 shifting** going to other side of corrugated tube then make **3 windings** of tape and cut.



7. After taping, check the measurement and tape condition.

MEASURING TAPE



1. No flip-out tape
2. No peel-off tape
3. No loose tape
4. No missing tape
5. No wrong dimension
6. No wrong use of tape

Note:

Please use calibrated/verified measuring tape when getting the measurement.

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

NBC (Philippines)
MASTER COPY

DCC Stamp