



WORK INSTRUCTION END TAPE PRESSING PROCESS

Process Name/Title:

Product Name/Code: **5 Levercon / 17J796/17J924/17L544**

Customer: **TRP**

Purpose: ☐ PROTOTYPE

☐ PRE-LAUNCH

☒ MASSPRO

Effectivity Date:

May 10, 2021

Validity Date:

n/a

Document No.:

WI-ENG-PDE-096

Revision No.:

5

Page No.:

2 of 2

PARTS:

1. Assy parts

JIG

1. Pneumatic pressing jig

NO.

PROCESS NAME

WORK PROCEDURE/ ILLUSTRATION

TOOLS/PPE/QUALITY POINTERS

1

Wire harness setting to pressing jig
(Continuation)



4. After 20-30 seconds, pressing jig will automatically release.




5. Get the lever con using right hand.

1. No damage parts
2. No floating or peel-off tape
3. No foreign material

2

Visual inspection

After Pressing




2 seconds above




1 second

1. Check the end tape appearance.



Tape width



GOOD

NG

Peel off Tape

NOTE:

Replace the pressing foam from top to bottom every 500 shots

1. No damage parts
2. No floating or peel-off tape
3. No foreign material

CONFIDENTIAL: Any misuse or misappropriation, including unauthorized copying, reproduction in any form, disclosure or publishing of this document or any information herein is strictly prohibited.

**NBC (Philippines)
MASTER COPY**

DCC Stamp