


Strain at sensor O11 due to  
Truck 1 moving across bridge 705



Strain at sensor O12 due to  
Truck 1 moving across bridge 705

