


Strain at sensor T19 due to
Truck 1 moving across bridge 705



Strain at sensor T20 due to
Truck 1 moving across bridge 705

