


Exhibit K-5

Carbon Fiber Re-enforced Polymer (CFRP) wing panel



Spar cap

Catastrophic failure of Carbon Fiber Re-enforced Polymer (CFRP) wing panel showing severe delamination and fracture due to fatigue

Spar
Mechanical fastening to spar cap

The above unannotated photo and description can be found at the following link:
<https://www.flightglobal.com/picture-boeing-completes-destructive-test-on-787-wing-box/83930.article>