

Component Failures

1998

2023

Recall Event Count

Total Volume Affected

Median Event Volume

18.85K


893M

565

Component

- Select all
- AIR BAGS
- BACK OVER PREVENTION
- CHILD SEAT
- COMMUNICATION
- ELECTRICAL SYSTEM
- ELECTRONIC STABILITY CONTROL
- ENGINE
- ENGINE AND ENGINE COOLING
- EQUIPMENT
- EQUIPMENT ADAPTIVE/MOBILITY
- EXTERIOR LIGHTING
- FORWARD COLLISION AVOIDANCE
- FUEL SYSTEM, DIESEL
- FUEL SYSTEM, GASOLINE
- FUEL SYSTEM, OTHER


Vehicles Affected by Year and Component




Largest Volume Recalls

- AIR BAGS
17600000
- CHILD SEAT
4176601
- ELECTRICAL SYSTEM
5877718
- EQUIPMENT
2864670
- LATCHES/LOCKS/LINKAGES
5641577
- POWER TRAIN
2925968
- SERVICE BRAKES, HYDRAULIC
3456719
- STRUCTURE
3662211
- TIRES
32000000
- VEHICLE SPEED CONTROL
4500000

Top 10 Sum Units Recalled




Top 10 Mean Units Recalled



Corrective Actions


Component	Frequency
EQUIPMENT	8483
ELECTRICAL SYSTEM	5031
STEERING	3309
SUSPENSION	3096
SERVICE BRAKES, HYDRAULIC	2741
POWER TRAIN	2641
AIR BAGS	2590
STRUCTURE	2534
FUEL SYSTEM, GASOLINE	2472
ENGINE AND ENGINE COOLING	2119
EXTERIOR LIGHTING	2086
SERVICE BRAKES, AIR	2014
TIRES	1959
SEAT BELTS	1934
SEATS	1407
VISIBILITY	1364
WHEELS	1005
EQUIPMENT ADAPTIVE/MOBILITY	785
VEHICLE SPEED CONTROL	731
LATCHES/LOCKS/LINKAGES	714
TRAILER HITCHES	642
PARKING BRAKE	618

Frequency by Action Taken




Workflow Analysis

Funnel: Top 20 Key Workflows by Volume Affected



Most Common Workflows by Event Count, Component



Raw Data

Report Received Date	NHTSA ID	Manufacturer	Mfr Campaign Number	Recall Type	Component	Potentially Affected	Subject
10 March 2023	23V161000	Kibbi, LLC	NR (Not Reported)	Vehicle	LATCHES/LOCKS/LINKAGES	63	Entry Door Latch Failure
10 March 2023	23V162000	Ford Motor Company	23S12	Vehicle	SERVICE BRAKES, HYDRAULIC	1280726	Front Brake Hoses May Rupture
10 March 2023	23V160000	Ford Motor Company	23C04	Vehicle	EXTERIOR LIGHTING	2716	Inoperative Trailer Taillights/FMVSS 108
10 March 2023	23V164000	Ford Motor Company	23S11	Vehicle	SERVICE BRAKES, HYDRAULIC	644	Rear Caliper Bolts Not Tightened Correctly
10 March 2023	23V165000	Ford Motor Company	23C05	Vehicle	BACK OVER PREVENTION	1651	Rearview Camera Malfunction/FMVSS 111
10 March 2023	23V163000	Ford Motor Company	23S10	Vehicle	VISIBILITY	222454	Windshield Wipers may Fail
09 March 2023	23E020000	Gilbarco, Inc.	NR (Not Reported)	Equipment	ELECTRICAL SYSTEM	10000	Cracked Capacitor May Cause Overheating
09 March 2023	23E019000	Chrysler (FCA US, LLC)	21A	Equipment	SERVICE BRAKES, HYDRAULIC	330	Hydraulic Control Unit Malfunction
09 March 2023	23V158000	Honda (American Honda Motor Co.)	NDA, QDB, BDC, MDD	Vehicle	SEAT BELTS	448613	Seat Belt Buckle May Not Latch
09 March 2023	23V159000	Rivian Automotive, LLC	FSAM-1185	Vehicle	AIR BAGS	30	Side Curtain Air Bag Improperly Secured
08 March 2023	23E018000	AROW Global Corp	NR (Not Reported)	Equipment	STRUCTURE	1500	Emergency Exit Window Latch May Fail/FMVSS 217
08 March 2023	23V154000	Navistar, Inc.	23506	Vehicle	ELECTRICAL SYSTEM	791	Battery Box May Detach
08 March 2023	23V157000	Eveland's Inc.	NR (Not Reported)	Vehicle	EQUIPMENT	0	Damaged Cooktop Control Valves May Leak Gas
08 March 2023	23V153000	Navistar, Inc.	23505	Vehicle	POWER TRAIN	660	DRIVESHAFT SEPARATION
08 March 2023	23V156000	Spartan Fire, LLC	23007	Vehicle	POWER TRAIN	166	Fire Truck Water Pump May Fail
08 March 2023	23V152000	Bentley Motors, Inc.	RE23/03 (RC68)	Vehicle	AIR BAGS	1610	Seat Air Bag May Tear/FMVSS 214 & 208
08 March 2023	23V155000	Ford Motor Company	23S09	Vehicle	STEERING	343	Steering Wheel May Lock-Up While Driving
07 March 2023	23E017000	SAF-Holland	NR (Not Reported)	Equipment	SUSPENSION	349	Lower Control Arm May Fail
07 March 2023	23V151000	Grand Design RV, LLC	910033	Vehicle	TIRES	105	Incorrect Tire Information on Label/FMVSS 110
07 March 2023	23V149000	Kia America, Inc.	SC263	Vehicle	AIR BAGS	188912	Side Curtain Air Bags May Not Deploy Properly
07 March 2023	23V148000	Terex Advance Mixer, Inc.	NR (Not Reported)	Vehicle	STEERING	20	Steer Axle Fasteners Not Tightened Properly
06 March 2023	23V146000	Triumph Motorcycles America, Ltd.	SRAN 606	Vehicle	SERVICE BRAKES, HYDRAULIC	988	Brake Disc May Detach
Total						1236869009	