



**On Point Locating, Inc.**  
1170 Lincoln Avenue, Suite 4,  
Holbrook, N.Y. 11741  
Phone: (631) On Point  
Fax: (631) 589-1157

## Sample Job Report

<b>I. Overview / Description</b>	page 1
<b>II. Job Site Sketch</b>	page 2
<b>III. Thermal Imaging Photographs</b>	page 3

**Date:**

**Job Site:**


**Client:**

**Telephone:**

**Invoice to:** Client

**Total Hours Onsite:** 2

**Description:**



On Point personnel worked to locate a heat pipe leak in the slab. Using the equipment described, the leak was determined to be in the kitchen floor, in the area depicted in the *Job Site Sketch* (II). The thermal camera captured the attached *Thermal Imaging Photographs* (III). The plumber is scheduled to perform the slab excavation and leak repair on Friday, Feb. 21, at 8:00 AM. The vinyl tiles in the kitchen will need to be removed.

**On Point Personnel On Site:**

- Michael Carty

**Equipment On Site:**

- LD-12 leak detector
- FLIR-E63900 thermal camera

**Other Personnel On Site:**

- Plumbing Company: Employee Name
- Tenant: Tenant Name




**On Point Locating, Inc.**  
1170 Lincoln Avenue, Suite 4,  
Holbrook, N.Y. 11741  
Phone: (631) On Point  
Fax: (631) 589-1157

## Sample Job Report

- I. Overview / Description
- II. Job Site Sketch**
- III. Thermal Imaging Photographs

(not to scale)









**On Point Locating, Inc.**  
1170 Lincoln Avenue, Suite 4,  
Holbrook, N.Y. 11741  
Phone: (631) On Point  
Fax: (631) 589-1157

## Sample Job Report

- I. Overview / Description
- II. Job Site Sketch
- III. Thermal Imaging Photographs**

*Images captured with FLIR-E63900 thermal camera.*



infrared photographs or  
other data gathered on site