

TECHNICAL SERVICE JOB CARD

JOB CARD NO: **40814**

CUSTOMER & SERVICE DETAILS

Client Name:	KCB	Service Date:	5/05/2023		
Personnel Name:	David Agutu	Start Time:	1530	End Time:	1553
Site Name:	KABIANGA ATM Kericho	Town:	Kericho town		

EQUIPMENT DETAILS

NO.	EQUIPMENT MODEL	SERIAL NO.	FAULT DESCRIPTION/STATUS
1.	Trip-Lite	Inverter	Faulty Identification
2.	ABB UPS		
3.			

EQUIPMENT ENVIRONMENT

Cleanliness	✓
Ac & Ventilation	✓
Recommendation	✓

ACTIONS/ ACTIVITIES CARRIED OUT/ ISSUES NOTED

- KPLC Power checked and found normal was reported there was black out
- All connection checked and found okay.
- Battery voltage tested and found okay but with low back up time.


BATTERY READINGS

No. of Strings:	2	Battery Qty:	4	Rating:	12 V 200Ah	Total Voltage:	24V		
1. 12.5V	2. 12.6V	3. 12.7V	4. 12.5V	5. 12.5V	6.	7.	8.	9.	10.
11.	12.	13.	14.	15.	16.	17.	18.	19.	20.
21.	22.	23.	24.	25.	26.	27.	28.	29.	30.
31.	32.	33.	34.	35.	36.	37.	38.	39.	40.

RECOMMENDATIONS/ CONCLUSIONS

(12V 200AH) X 4pcs batteries need to be replaced.

SITE & CUSTOMER APPROVAL

Site Contact Person:	Thompson	Signature:		Date:	15/05/2023
Client Contact Person:		Signature		Date & Stamp:	