



https://



Emissions Monitoring Tool

[Home](#)[Emissions](#)[Admin](#)**VN-14550**

Emission of acid from valve packing.
Currently below threshold for operational shutdown.

Next Check Due: 20/11/23

Current Check Due: 01/11/23

Status: Checks Completed

PI-1314

Emission of nitrogen from pressure
gauge threaded connection. Currently
below threshold for operational
shutdown.

Next Check Due: 01/12/23

Current Check Due: 01/11/23

Status: Checks Completed

P-5050

Weep of high temperature lube oil from
pump casing.

Next Check Due: 10/11/23

Current Check Due: 01/11/23

Status: Checks Completed

Emissions
cards to scroll
horizontally.





https://



All Emissions

[Home](#)[Emissions](#)[Admin](#)

Title ▲	Location ^	Check Status	Date Raised ▼
VN-14550	Valve Deck	Completed	02/03/2022
PI-1314	Utilities Module	Completed	04/04/2021
P-5050	Upper Pump Station	Completed	01/02/2023
K-3200	Compressor House	Outstanding	21/08/2021
RV-1138	Relief valve deck	Outstanding	10/10/2019






https://



VN-14550

[Home](#)[Emissions](#)[Admin](#)

Emission of acid from valve packing.
Currently below threshold for
operational shutdown.



Latest Checks

Date ▲	Comments ^	Status ▼
01/09/23	No issues	<1 drop/min
05/08/23	No issues to report	<1 drop/min
08/07/23	No issues	<1 drop/min
01/06/23	No issues	<1 drop/min
01/09/23	No issues	<1 drop/min

[Add New Check](#)



https://



VN-14550 Checks

[Home](#)[Emissions](#)[Admin](#)

Enter New Check

Status	Comment
<p><input checked="" type="radio"/> < 1 drop/min (selected)</p> <p><input type="radio"/> > 1 drop/min</p> <p><input type="radio"/> no leak</p>	Checked valve and found leakage remains steady. Emptied spillage container underneath.

[Submit New Check](#)

FREEPIK ATTRIBUTIONS:

[Image of valve. Image by fanjianhua on Freepik](#)

[Image of gauge. Image by fanjianhua on Freepik](#)