

CENTRAL INTELLIGENCE AGENCY

15127-66

This document contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, USC, Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

~~CONFIDENTIAL~~

COUNTRY

UNIDENTIFIED

4 MAY 1966

REPORT NO.

SUBJECT

Exploitation of Metallic Fragment
from Unidentified Flying Object

DATE DISC

4 MAY 66

NO. PAGES

1

EXPLOITATION OF METALLIC FRAGMENT
FROM UNIDENTIFIED FLYING OBJECT

REFERENCES

DATE OF

APRIL 1966

PAGE

April 1966

PAGE

PAGE

SOURCE:

On file in CIA Library is an exploitation report on a metallic fragment approximately 2"x2"x1", recovered near Kerekene, Republic of the Congo. The fragment was recovered by ground search after a UFO fell to earth in the area. The report concludes that the fragment was originally part of an electrical component and was constructed of 0.010-inch thick silicon-steel laminate.

~~CONFIDENTIAL~~

The dissemination of this document is limited to those agencies and persons duly authorized to receive information of this nature. It is to be controlled and its use is to be limited to the purposes for which it was prepared. It is to be destroyed when it is no longer needed for the purposes for which it was prepared. It is to be handled in accordance with the provisions of the Espionage Laws, Title 18, USC, Secs. 793 and 794.

DIFFER

7649

NUMBER

0

23 24

1

2 2

3 3

4 4

AREA

5 5

6 6

7 7

8 8

②

Approved for Release

2/2010

13

CONFIDENTIAL

EXPLOSION REPORT

1. FRAGMENT, METAL, RECOVERED IN THE REPUBLIC OF THE CONGO,
 BELIEVED TO BE AN UNIDENTIFIED FLYING OBJECT
 (COUNTRY UNIDENTIFIED) (U)
 REF: 25500

SECTION I. (C) Purpose (U)

1. (C) The purpose of this report is to present the results of the exploitation of a metallic fragment recovered near the town of Kerehema in the Republic of the Congo. The recovery was the result of a ground-level search which was conducted after an unidentified flying object exploded and fell to earth in the area. The sighting and recovery took place sometime between 10 and 15 October 1963. Other than a reported east-to-west direction of flight for the UFO, specific observation and recovery details are lacking.

SECTION II. (C) Description (U)

2. (C) Details concerning the exact location and characteristics of impact are unknown. However, the appearance of the fragment indicated exposure to high temperatures prior to impact (earth). The impact of the specimen had little or no effect on its final condition or appearance. The fragment weighed 0.11g, had an indefinite density of approximately iron and measured 2.25 x 1.75 x 1.0 inches. The top and side views of the specimen were rounded and appeared to have been shaped by heating and melting. This is illustrated in Figures 1 and 2. The U-shaped groove, visible in Figure 1, is the outline of an insert of steel that differs materially from the rest of the specimen. Figure 3 shows the side type of the end shown in Figure 1.

CONFIDENTIAL
 10-12-63
 25500

POOR ORIGINAL

CONFIDENTIAL

and was composed of six machined or formed T-shaped fins extending along the major axis of the fragment.

SECTION III. (C) Conclusions:

3. (C) The fragment was originally part of an electrical component and could be identified as a motor, generator armature, or associated electrical regulator or device.

4. (C) The fragment was constructed of .010-inch thick silicon steel laminates stacked on a central mild steel core or shaft.

5. (C) Materials, processes, dimensions, etc., as such, prevent determination of exact origin (country).

6. (C) Surface appearance and microstructure of the specimen indicates exposure to temperatures in excess of 2850° F.

SECTION IV. (C) Explanation:

7. (C) The recovered fragment was .61 inches in diameter and had a density closely approximating that of iron. The fragment was found on heavy oxide was found. The fragment was found at temperatures in excess of 2850° F. While there are no indications of impact, the fused metal, as shown in Figures 4 and 7, would substantiate the conclusion that the fragment was moving at a high velocity when it was hit.

8. (C) Fabrication of the fragment was accomplished utilizing more or less standard procedures for fabricating electric motor armatures.

Armature laminates were stamped (punched) from approximately .012-inch sheet steel, copper-plated, and assembled on a mild steel shaft approximately .435 inches in diameter. Following assembly, the laminates were joined by soldering or diffusion-bonding of the copper-

CONFIDENTIAL

CONFIDENTIAL

placing. This can be accomplished by slightly compacting the laminate assembly and heating in a furnace. Temperature required for bonding of the copper depends upon the degree compaction or pressure; the higher pressures requiring proportionately lower temperatures.

9. (C) A cross-section (transverse to length of the specimen) is shown in Figure 3. The light-colored lines are the edges of individual laminates, caused by cutting at an angle to, instead of parallel to, the laminates. These lines or petals are "T" shaped. This shape is used to help winding wire in place and is found on high RPM motors. The melted condition of some of the "T's" is indicative of the high heating conditions experienced. The outer surface of the armature shaft is serrated to prevent axial slippage of the laminates.

10. (C) The lamination or stacking of individual laminates is clearly illustrated in Figure 6. The space between laminates on the fin at the top of the photograph is due to the melting and slumping of the copper during the high temperature exposure of the specimen. Some of the copper has been removed from the fin at the bottom of the photograph. A cross-section of this area is shown in Figures 7 and 8.

11. (C) Another result of intense heating was the increased grain size of the steel laminates' microstructure. The microstructure of the laminates shown in Figures 9 and 10 illustrates grain sizes that are comparable to Category 2 of ASTM A-262.

Large grain size indicates the high temperature exposure.

~~CONFIDENTIAL~~

intense heat and then cooled at a comparatively slow rate.

12. (C) The light material between the laminations in Figure 9 is plated copper that melted and flowed between the laminations when the entire specimen was hot. A photomicrograph of this is shown in Figure 11.

13. (C) Analysis of the steel discloses the following:

Element	Percent Present (Calcd)
Carbon	
Manganese	
Silicon	
Nickel	less than 0.10
Chromium	0.87
Molybdenum	less than 0.01

14. (C) Chemical composition of the steel laminations was as follows:

Element	Percent Present (Calcd)
Manganese	0.25
Silicon	(0.5)
Nickel	less than 0.10
Chromium	
Molybdenum	less than 0.01

~~CONFIDENTIAL~~

Figure 1

Figure 1 Top View of the device





Figure 2 Side View of the device

DO NOT ORIGINAL



UNCLASSIFIED




Figure 3. Cross Section (Orientation to the Length of the Specimen)
Magnification: 2X/10



POOR ORIGINAL




Figure 7 Micrograph cross-section of
laminated area
Magnification 7,750 X




Figure 8 Micrograph cross-section of
laminated area
Magnification 7,750 X

UNCLASSIFIED

UNCLASSIFIED




Figure 9.10 Micrograph of
Laminated Structure
Magnification 65x
(X-ray Microscopy)

POOR ORIGINAL




Figure 11.4 Photomicrograph of: High
Magnification of Material Between the Laminations
Magnification 790X
Oxide Acids Etchant (AC)
Oxide Acids Etchant

Legend