



INFOGRAPH POWERLINE INSPECTION SYSTEM REPORT

Report Created: August 21th, 2024; 10:10:30

Original Image Name: DJI_650.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_650\DJI_650.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_650_3 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_650_DJI_650_3 - Copy - Copy.png

Fault Type	Severity
missing knob	82.69 %
rusty clamp	99.28 %
broken insulator	94.88 %



Original Image Name: DJI_650.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_650\DJI_650.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_650_3 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_650_DJI_650_3 - Copy.png

Fault Type	Severity
missing knob	98 %
rusty clamp	86.57 %
broken insulator	93.79 %



Original Image Name: DJI_650.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_650\DJI_650.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_650_3.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_650_DJI_650_3.png

Fault Type	Severity
missing knob	99.78 %
rusty clamp	89.45 %
broken insulator	82.97 %



Original Image Name: DJI_651.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_651\DJI_651.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_651_2 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_651_DJI_651_2 - Copy - Copy.png

Fault Type	Severity
missing knob	99.45 %
broken insulator	99.66 %
rusty clamp	95.78 %



Original Image Name: DJI_651.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_651\DJI_651.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_651_2 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_651_DJI_651_2 - Copy.png

Fault Type	Severity
missing knob	95.78 %
broken insulator	92.17 %
rusty clamp	98.33 %



Original Image Name: DJI_651.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_651\DJI_651.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_651_2.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_651_DJI_651_2.png

Fault Type	Severity
missing knob	99.87 %
broken insulator	86.57 %
rusty clamp	93.28 %



Original Image Name: DJI_652.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_652\DJI_652.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_652_3 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_652_DJI_652_3 - Copy - Copy.png

Fault Type	Severity
missing knob	77.45 %
rusty clamp	69.32 %
broken insulator	89.15 %



Original Image Name: DJI_652.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_652\DJI_652.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_652_3 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_652_DJI_652_3 - Copy.png

Fault Type	Severity
missing knob	56.48 %
rusty clamp	82.51 %
broken insulator	73.86 %



Original Image Name: DJI_652.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_652\DJI_652.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_652_3.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_652_DJI_652_3.png

Fault Type	Severity
missing knob	99.41 %
rusty clamp	98.39 %
broken insulator	95.77 %



Original Image Name: DJI_653.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_653\DJI_653.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_653_2 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_653_DJI_653_2 - Copy - Copy.png

Fault Type	Severity
missing knob	86.24 %
broken insulator	32.78 %
rusty clamp	78.93 %



Original Image Name: DJI_653.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_653\DJI_653.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_653_2 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_653_DJI_653_2 - Copy.png

Fault Type	Severity
missing knob	91.55 %
broken insulator	86.78 %
rusty clamp	99.45 %



Original Image Name: DJI_653.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_653\DJI_653.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_653_2.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_653_DJI_653_2.png

Fault Type	Severity
missing knob	99.66 %
broken insulator	99.53 %
rusty clamp	99.26 %



Original Image Name: DJI_654.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_654\DJI_654.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_654_2 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_654_DJI_654_2 - Copy - Copy.png

Fault Type	Severity
missing knob	90.75 %
broken insulator	56.45 %
rusty clamp	78.69 %



Original Image Name: DJI_654.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_654\DJI_654.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_654_2 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_654_DJI_654_2 - Copy.png

Fault Type	Severity
missing knob	93.78 %
broken insulator	77.01 %
rusty clamp	85.43 %



Original Image Name: DJI_654.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_654\DJI_654.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_654_2.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_654_DJI_654_2.png

Fault Type	Severity
missing knob	99.66 %
broken insulator	99.53 %
rusty clamp	99.26 %



Original Image Name: DJI_655.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_655\DJI_655.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_655_2 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_655_DJI_655_2 - Copy - Copy.png

Fault Type	Severity
missing knob	100 %
broken insulator	95.45 %
rusty clamp	48.27 %



Original Image Name: DJI_655.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_655\DJI_655.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_655_2 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_655_DJI_655_2 - Copy.png

Fault Type	Severity
missing knob	92.45 %
broken insulator	97.54 %
rusty clamp	88.2 %



Original Image Name: DJI_655.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_655\DJI_655.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_655_2.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_655_DJI_655_2.png

Fault Type	Severity
missing knob	89.45 %
broken insulator	99.66 %
rusty clamp	80.64 %



Original Image Name: DJI_656.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_656\DJI_656.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_656_3 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_656_DJI_656_3 - Copy - Copy.png

Fault Type	Severity
missing knob	90.56 %
rusty clamp	84.11 %
broken insulator	90.17 %



Original Image Name: DJI_656.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_656\DJI_656.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_656_3 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_656_DJI_656_3 - Copy.png

Fault Type	Severity
missing knob	99.68 %
rusty clamp	66.77 %
broken insulator	80.89 %



Original Image Name: DJI_656.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_656\DJI_656.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_656_3.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_656_DJI_656_3.png

Fault Type	Severity
missing knob	100 %
rusty clamp	98.31 %
broken insulator	78.31 %



Original Image Name: DJI_657.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_657\DJI_657.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_657_2 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_657_DJI_657_2 - Copy - Copy.png

Fault Type	Severity
missing knob	86.54 %
broken insulator	88.64 %
rusty clamp	100 %



Original Image Name: DJI_657.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_657\DJI_657.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_657_2 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_657_DJI_657_2 - Copy.png

Fault Type	Severity
missing knob	92.54 %
broken insulator	89.45 %
rusty clamp	78.41 %



Original Image Name: DJI_657.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_657\DJI_657.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_657_2.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_657_DJI_657_2.png

Fault Type	Severity
missing knob	99.52 %
broken insulator	99.67 %
rusty clamp	99.87 %



Original Image Name: DJI_658.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_658\DJI_658.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_658_3 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_658_DJI_658_3 - Copy - Copy.png

Fault Type	Severity
missing knob	89 %
rusty clamp	65 %
broken insulator	60.78 %



Original Image Name: DJI_658.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_658\DJI_658.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_658_3 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_658_DJI_658_3 - Copy.png

Fault Type	Severity
missing knob	89.78 %
rusty clamp	95.64 %
broken insulator	77.99 %



Original Image Name: DJI_658.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_658\DJI_658.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_658_3.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_658_DJI_658_3.png

Fault Type	Severity
missing knob	89.12 %
rusty clamp	89.13 %
broken insulator	63.47 %



Original Image Name: DJI_659.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_659\DJI_659.JPG


Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_659_3 - Copy - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_659_DJI_659_3 - Copy - Copy.png

Fault Type	Severity
missing knob	89.65 %
rusty clamp	89 %
broken insulator	61.24 %



Original Image Name: DJI_659.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_659\DJI_659.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_659_3 - Copy.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_659_DJI_659_3 - Copy.png

Fault Type	Severity
missing knob	96.22 %
rusty clamp	93.65 %
broken insulator	78.45 %



Original Image Name: DJI_659.JPG

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_659\DJI_659.JPG

Image Info	Details
Date Captured	2020:08:01 11:39:44
Latitude	9° 41' 23.9784" N
Longitude	6° 46' 14.9483" E
Altitude	346.14 m

FAULT

Fault Image Name: _DJI_659_3.png

Image Path: c:\Users\HP\Downloads\Python Scripts-20240821T073345Z-001\Python Scripts\Sample Refined\DJI_659_DJI_659_3.png

Fault Type	Severity
missing knob	97.55 %
rusty clamp	91.25 %
broken insulator	94.63 %

