

Initial Incident/Accident Report

Fill the Information Below	
Company: Rezayat company limited.	Date: 12/07/2021
Location: Wadi Sharma	Time: 10:40 AM
Project/ Site Name: Pipeline protection project(BGP)	Worst Potential Severity: 1 Actual Severity: 1
Person(s) Involved:	<input checked="" type="checkbox"/> Employee <input checked="" type="checkbox"/> Contractor <input type="checkbox"/> Others
1. Faiz Alam CB.no:- 29806 2. Rolando Lacanaria CB.no:- 33617 3. Mohammed Waleed Mustafa (CB.no:- 36493)	
Type of Incident: Client property damage.	
Choose an item. Client Property damage.	
Injury Location by Body Parts (Select one or more if necessary):	
Head	Chest
Face	Leg
Neck	Abdomen
Back	Stomach
Nose/ Ears	Shoulder
Hand	Arm
Wrist	Elbow
Fingers/ Thumb	Toes
Type of Injury Sustained (Select one or more if necessary):	
Fracture	Cut/ Laceration
Loss of Sight	Loss of Consciousness
Dislocation	Crush Injury
Abrasion	Suffocation
Scalping	Bruising
Heat	Amputation
Cold	Other(s)
Burn	X
Immediate Cause(s) (Select one or more if necessary):	
Safety Rule Violated	Lack of Resources
Lack of Task Skill	Method Deviation
Lack of Supervision	Poor Weather Conditions
Improper Lifting (MH)	Lack of Task Knowledge
Not Paying Attention	Lack of Communication
Human Error	Incorrect Tools/Equip
Inadequate PPE	Defective Tools
Animals	Violence
Heat Stress	STF Above Ground
Misuse of Hand Tools	Grinding/ Welding
Hit by Static Machinery	Heavy Equipment
Stress	Fatigue
Drugs/ Alcohol Related	Poor Housekeeping
Inadequate Lighting	Poor Team Work
No Risk Assessment	Defective Equipment
Unprotected excavation	Improper Lifting (crane)
Unprotected Edge	Improper/ Poor Slings
Manual Handling	Hit by Vehicle
Other(s) :	
Equipment(s) Involved:	
Light Vehicle:	Heavy Vehicle:
Building:	Structure:
Other(s):	
Plant Equipment:	Static Plant Equipment:
Scaffold:	Excavation:
Description of the Event:	
Around 10:40 AM backhoe loader entered in to the prohibited area with the permission of supervisor to remove the soil heap which is collected from the excavated area which was instructed by assistant foreman Mr. Rolando. While the equipment clearing the soil from the location, the fiber optical cable was gets damaged which is buried 10cm below the soil. And it has not been reported to the site safety officer and PM by the supervisor. Client notice the shutdown of the connection in line and reached the location then reported to project manager.	
Immediate Action(s) Taken to Prevent Reoccurrence (If Any):	
Barriaded the cable location. Rectified the damages with the support of technician assigned by client. (Amount paid by RCL PM 2,000 SAR)	
Person Created the Report:	
Name: Obeysullah	Position: HSE officer
Signature: [Signature]	Date: 12 / 07 / 2021

Note: This form is to be submitted four (4) hours after the incident occurred.

Revision Dated: 24 June 2015

