



Rezayat Company Limited
HSE Department
Notification Report

RCL-HSE-FM-07.4 - Version 1.0 Rev. Nov 2020

Company:	Rezayat Company Limited	Date:	Dec-24-2020
Location:	Yanbu	Time:	11:55 am

Project/Site Name:	Yanbu (Royal Commission)	Actual Severity:	None	Worst Potential Severity:	5
---------------------------	--------------------------	-------------------------	------	----------------------------------	---

Persons Involved:	30035218 - Mohamoud Ibrahim Abdel Aziz Hamed, 30036081 - Mohammad Rayees, 30037290 - Ray Oronan Valdehueza, 30038422 - Elsayed Mohamed Dif Elsayed
Injury Location by Body Parts:	None
Type of Injury Sustained:	None
Immediate Cause(s):	Human Error, Lack of Communication
Equipment(s) Involved:	Plant Equipment
Description of the Event:	During the demolition work of boundary wall with the heavy equipment-breaker, live electrical cable was exposed which was buried very close to the precast wall with in 20 cm down to the earth without following any safety standards for placing the electrical cable.
Immediate Action(s) Taken to Prevent Reoccurrence:	Stopped the activity. Reported to project manager and Site Engineer for coordinating with concern department. Trail pit was done to confirm same depth of buried cable in other area

Person Created the Report:	Signature:
30039679 - Rejenson Fernando Ruban (Officer II - Safety)	

