

Name of Employee	Hussain	Badge No.	Sub con supervisor		Actual Severity:	1
Safety Awareness Training Date	10/19/2019	Proof of Training	Induction		Worst Potential Severity:	3
Name of Line Manager	Mustafa Ali	Badge No.	3104094	Profession/ Designation	Project Manager	
Name of Supervisor	Ibrahim Sabry	Badge No.	31032055			
Division / Department	Civil Department	Project Name	097-C76 R	Project Location	JUC	
Place of the Incident/Injury	Area 1 (PART 2)	Date of Incident	4/7/2021	Time of Incident	03:30 PM	
Nature of the Incident/Injury	Occupational Incident/Injury	No	Near Miss	Other, Please specify :		
	Road Traffic Incident/ Injury	No	Yes			
Brief Description of the Incident/Injury	During concrete pouring in the column, the shuttering failed and as a result a considerable amount of concrete spilled out from the bottom of the shuttering. At the time of incident, the area below was barricaded properly. No property damage or injury was reported.					
Details of the Injury (Specify affected body parts)	N/A					
First Aid Given?	No	Name of First Aider				
Name of Hospital where patient was treated/transferred				Address/Location of the hospital		
Medical leave given by administering Hospital/Clinic or Doctor	No	Number of Days		Hospitalization	No	
Property damage	No	Estimated percentage of damage		Estimated Cost of damaged (SAR)	N/A	
Property Details	Type / Function of the property	N/A		Location of affected property	N/A	
	Name of Manufacturer	N/A				
	Model of the Property	N/A		Plate Number	N/A	
	Vehicle Registration Number	N/A		Company Fleet Number	N/A	

Was Pre- Task / Toolbox meeting conducted	Yes	Was the person using required Personal Protective Equipment (PPE)	Yes
Specify the Personal Protective Equipment (PPE)	Helmet, safety shoes, vest, gloves and goggles, Safety Harness		
What was the injured person/employee doing at the time of the incident?	N/A		
What was the machine/equipment doing at the time of the incident?	NA		
What was the material/s / substance/s doing at the time of the incident	Concrete pouring in the column		
Immediate Cause/s of the Incident/injury: .Due to failure of shuttering, Concrete spilled out on bottom to the ground.			
Root Cause/s of the Incident/injury:	People: N/A		
	Process / Procedure:		
	Equipment: N/A		
	Workplace: N/A		
Corrective Action to prevent reoccurrence:	Elimination: N/A		
	Substitution: N/A		
	Engineering Control: Shuttering work should be erected as per the drawing. And as per the concrete capacity strength.		
	Administrative Control: Prior to concrete pouring, shuttering of columns should be double inspected.		
PPE: Ensure to use all required ppe, s during concrete pouring works.			
Were there any witnesses?	None	Type of witness/s	Employee
Witness Details -		Badge Number	Mobile Number

Witness Statement:

Initial Investigation Conducted by: Krishna Pillai

Rehmat Ullah


Noted by:

[Signature]

Date

4/7/2021

Additional Details:



Investigation Report Verified by:

Noted by:

Date

4/7/2021