

[Home](#)

# Problem Report

**Project:** GPATS-CIC  
**Number:** 73     
**Created:** Nov 13 2017 2:09PM  
**State:** Pending Analysis

**Title:** View TPS Technical Manual error incorrect

**Problem:** When the "View TPS Technical Manual" button is clicked on the ATS Menu, if there is not a IETM located on the TPS disc, then an error is thrown. An error should be thrown, however, the message that is on the error popup box is incorrect. It is reporting the directory location of VXI\_RESMAN which does not exist.  
 (Robert.Giumarra)

**Analysis:**  
 ()

**Action Taken:**  
 ()

**Implementation:**  
 ()

**Version:**  
**Date:**

[Home](#)

# Problem Report

**Project:** GPATS-CIC  
**Number:** 75     
**Created:** Nov 13 2017 2:20PM  
**State:** Pending Analysis

**Title:** FG Internal Trigger

**Problem:** The test procedure 1.2.0.3 calls for the Internal Trigger of the Function Generator to be able to accommodate 15 micro second and 1ks. However, (Robert.Giumarra) the Function Generator soft front panel internal trigger will not accept 15 micro seconds.

**Analysis:**  
 ()

**Action Taken:**  
 ()

**Implementation:**  
 ()

**Version:**  
**Date:**

[Home](#)

# Problem Report

**Project:** GPATS-CIC**Number:** 76

Submit

Prev.

Next

**Created:** Nov 13 2017 2:24PM**State:** Pending Analysis**Title:** RF Counter Can't Get Out of Simulation Mode**Problem:**

(Robert.Giumarra)

The 1.0.2.0 test procedure states to select each listed button under Mode Control to ensure visible operation. When the simulation button is clicked, it does check and function properly. However, the simulation button cannot be de-selected after it is originally clicked. The CIC software needs to be modified to fix this issue.

**Analysis:**

()

**Action Taken:**

()

**Implementation:**

()

**Version:****Date:**