

Crackterized Result

The image characterized as: Contains Crack

Length: 0.11

Width: 0.02

Positive Crack Probability: 59.21%

Negative Crack Probability: 40.79%

Location of Crack: Corner Crack/s

Crack Type: Drying Shrinkage Crack/s

Crack Progression: Creep Crack Growth

