

Crackterized Result

The image characterized as: No Detected Crack

Length: 0

Width: 0

Positive Crack Probability: 27.31%

Negative Crack Probability: 72.69%

Location of Crack: None

Crack Type: None

Crack Progression: None

