

The image classified as: Contains Crack

Length: 3.31 cm

Width: 20.28 mm

Orientation: horizontal

Positive Crack Probability: 73.11%

Negative Crack Probability: 26.89%

Location of Crack: Crack/s on Column

Crack Type: Settlement Crack/s

Crack Progression: Overload Crack

Growth

Date Added: None

