

Crackterized Result



The image characterized as: **No Detected Crack**

Length: **0 cm**

Width: **0 mm**

Positive Crack Probability: **27.10%**

Negative Crack Probability: **72.90%**

Location of Crack: **Column**

Date Added: **2023-05-10 16:20:21**

Remarks: