



Crackterize Result

The image characterized as: **No Detected Crack**

Length: **0 cm**

Width: **0 mm**

Positive Crack Probability: **27.10%**

Negative Crack Probability: **72.90%**

Location of Crack: **Slab (Suspended)**

Name of Project: **renmaee**

Name of Folder: **rename**

Date Added: **2023-05-09 22:18:42**

Remarks: **HAHAHAHHAHA**