



The image characterized as: **No Detected Crack**

Length: **0 cm**

Width: **0 mm**

Positive Crack Probability: **27.10%**

Negative Crack Probability: **72.90%**

Location of Crack: **Beam**

Name of Project: **test**

Name of Folder: **test folder**

Date Added: **2023-05-15 23:20:24**

Remarks: