

## Crackterized Result

The image characterized as: Contains Crack

Length: 7.46

Width: 15.94

Positive Crack Probability: 73.03%

Negative Crack Probability: 26.97%

Location of Crack: Horizontal Crack/s on Wall

Crack Type: Structural Crack/s

Crack Progression: Environmental Crack/s

Date Added: 2023-04-14 21:52:48

