


All Defects		Lot 9/Tract 6260	
<div><div></div>Anlin Windows</div>			
Code: ZZ_705	Location: Bedroom 4	Description: Window in second floor loft area lock is not working - left side window	Incomplete
Category: Windows	Type: Window operation		
Partner: Anlin Windows			
Code: ZZ_715	Location: Bedroom 3	Description: Slide and glide windows	Incomplete
Category: Windows	Type: Window operation		
Partner: Anlin Windows			
Code: ZZ_716	Location: Bathroom 2	Description: Window in bath 2 above the shower doesn't open and lock doesn't work	Incomplete
Category: Windows	Type: Window operation		
Partner: Anlin Windows			
<div><div></div>Cabinet Connection</div>			
Code: ZZ_711	Location: Bathroom 4	Description: Vanity cabinet in bath 4 has nail holes that need to be filled	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_718	Location: Kitchen	Description: Cabinet touch up on side of fridge surround Upper door left side of stove has some jagged chips inside the door	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_724	Location: Bathroom 1	Description: Master vanity left side nail holes on top of left side drawer Chip under center vanity Master right side vanity needs touch up	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_725	Location: Bathroom 1	Description: Cabinet above the toilet in master bath needs touch up in a couple spots outside door and inside	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			

All Defects		Lot 9/Tract 6260	
Code: ZZ_725			
Category: Cabinets	Location: Bathroom 1	Description: Cabinet above the toilet in master bath needs touch up in a couple spots outside door and inside	Incomplete
Partner: Cabinet Connection	Type:		
<div><div></div>De Young Properties</div>			
Code: ZZ_706			
Category: Drywall	Location: Bedroom 4	Description: Drywall chips at left side window in loft area needs touch up	Incomplete
Partner: De Young Properties	Type: Crack/gash/ding		
Code: ZZ_707			
Category: Drywall	Location: Bedroom 4	Description: Drywall nail pop in bedroom 4 In closet several spots of dings - 4-5 spots	Incomplete
Partner: De Young Properties	Type: Crack/gash/ding		
Code: ZZ_712			
Category: Drywall	Location: Stairwell	Description: Drywall nail pops stair case	Incomplete
Partner: De Young Properties	Type: Crack/gash/ding		
Code: ZZ_713			
Category: Drywall	Location: Dining Room	Description: Ding in bullnose in dining room	Incomplete
Partner: De Young Properties	Type: Crack/gash/ding		
<div><div></div>Everlast Paint</div>			
Code: ZZ_708			
Category: Paint	Location: Bedroom 4	Description: Caulking drop on baseboard in bedroom 4	Incomplete
Partner: Everlast Paint	Type: Cleanup		
Code: ZZ_709			
Category: Paint	Location: Bedroom 4	Description: Paint touch up on ceiling in left area upstairs	Incomplete
Partner: Everlast Paint	Type: Cleanup		
<div><div></div>John Ventresca Co</div>			

Code: ZZ_720			
Category: Fireplace Surround	Location: Great Room	Description: Crack in fireplace surround several spots	Incomplete
Partner: John Ventresca Co	Type: Mortar cracked/missing		
<div><div></div>LinkUs</div>			
Code: ZZ_703			
Category: Low Voltage Electrical	Location: Bedroom 4	Description: Reattach alarm sensor in window in loft area - left side window of upstairs living area	Incomplete
Partner: LinkUs	Type:		
<div><div></div>Matthews Quality Construction</div>			
Code: ZZ_722			
Category: Millwork	Location: Great Room	Description: Crack in millwork surrounding the fireplaxe	Incomplete
Partner: Matthews Quality Construction	Type:		
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_719			
Category: Drywall	Location: Great Room	Description: Drywall touch up of nail holes on either side of all the floating shelves in the great room	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
Code: ZZ_721			
Category: Drywall	Location: Dining Nook	Description: Drywall touch up needed in dining room area	Incomplete
Partner: Ohanians Drywall	Type: Crack/gash/ding		
<div><div></div>Quality Plumbing</div>			
Code: ZZ_714			
Category: Plumbing	Location: Bedroom 5	Description: Toilet seat in half bath needs to be adjusted	Incomplete
Partner: Quality Plumbing	Type:		
<div><div></div>Tile Interiors</div>			

All Defects		Lot 9/Tract 6260		
Code: ZZ_704	Location: Bathroom 4	Description: Grout touch up in bathroom 4 next to tub - tub to tile	Incomplete	
Category: Tile	Type: Grout cracked/missing			
Partner: Tile Interiors				
Code: ZZ_710	Location: Bathroom 4	Description: Grout crack at base of vanity in bath 4	Incomplete	
Category: Tile	Type: Grout cracked/missing			
Partner: Tile Interiors				
Code: ZZ_717	Location: Kitchen	Description: Grout crack counter top to backsplash in several places Chipped tile in backsplash above beverage center	Incomplete	
Category: Tile	Type: Grout cracked/missing			
Partner: Tile Interiors				
 Westech				
Code: ZZ_723	Location: Bedroom 1	Description: Push up can light in under stairs closet next to the master bedroom	Incomplete	
Category: Electrical	Type:			
Partner: Westech				