

All Defects		Lot 14/Tract 6260	
<div><div></div>Anlin Windows</div>			
Code: ZZ_673	Location:	Description: Missing screens on all windows	Incomplete
Category: Windows	Type:		
Partner: Anlin Windows			
Code: ZZ_697	Location:	Description: Master bed window won't latch	Incomplete
Category: Windows	Type:		
Partner: Anlin Windows			
<div><div></div>Cabinet Connection</div>			
Code: ZZ_679	Location: Kitchen	Description: Missing knob in kitchen under sink	Incomplete
Category: Cabinets	Type: Part missing		
Partner: Cabinet Connection			
Code: ZZ_680	Location: Kitchen	Description: Scratch by microwave and overn Scratches on either side of hood Scratch on pantry cabinets	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_694	Location:	Description: Cabinet scratch on laundry cabinet drawer face	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_700	Location:	Description: Left drawer in master bath off trac	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_701	Location: Bathroom 1	Description: Cabinet scratch on right vanity in master bath	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
<div><div></div>Everlast Paint</div>			

Code: ZZ_675	Location: Great Room	Description: 3 circles In great room and dining area cause from possible previous water leak	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_676	Location:	Description: Excess caulking in bonus room	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_682	Location:	Description: Paint touch up bullnose by bath 3	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_683	Location:	Description: Paint touch up bed 4 wall and baseboard	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_685	Location:	Description: Stairwell touch up on railing	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_686	Location:	Description: Clean paint off ballisters	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_695	Location:	Description: Paint upstairs hall by linen closet	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_696	Location:	Description: Paint bath 2 left of sink	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
Code: ZZ_702	Location:	Description: Paint touch up by bed 4 door trim	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			

Code: ZZ_689			
Category: Appliances	Location:	Description: Paint touch up bed 2	Incomplete
Partner: Ferguson	Type:		

 Granite Mountain Stone Design

Code: ZZ_684			
Category: Solid Surface	Location:	Description: Pink spot on quartz in bath 3	Incomplete
Partner: Granite Mountain Stone Design	Type:		

 HSI

Code: ZZ_699			
Category: Fire Sprinklers	Location:	Description: Missing fire sprinkler cap in master bedroom	Incomplete
Partner: HSI	Type:		

 John Ventresca Co

Code: ZZ_681			
Category: Fireplace Surround	Location:	Description: Grout by tile by brick fireplace. Large gap at bottom	Incomplete
Partner: John Ventresca Co	Type:		

 Ohanians Drywall

Code: ZZ_674			
Category: Drywall	Location:	Description: Drywall crack in ceiling of great room	Incomplete
Partner: Ohanians Drywall	Type:		

Code: ZZ_677			
Category: Drywall	Location:	Description: Drywall hole in bonus room by prewires	Incomplete
Partner: Ohanians Drywall	Type:		

Code: ZZ_678			
Category: Drywall	Location:	Description: Drywall by speaker in bonus room	Incomplete
Partner: Ohanians Drywall	Type:		

All Defects

Lot 14/Tract 6260

Code: ZZ_688	Location:	Description: Drywall touch up by prewire top of stairwell	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_690	Location:	Description: Drywall pop in bath 2 by tub	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_692	Location:	Description: Bullnose pop in hall by laundry room	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_693	Location:	Description: Nail pop on drywall on landing by master door	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_698	Location:	Description: Drywall by coax in master bed	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
<div><div></div>Tile Interiors</div>			
Code: ZZ_691	Location:	Description: Grout crack in bath 2 by tub	Incomplete
Category: Tile	Type:		
Partner: Tile Interiors			
<div><div></div>True Frame</div>			
Code: ZZ_687	Location:	Description: Floor squeak second stair from first landing	Incomplete
Category: Framing	Type:		
Partner: True Frame			