

All Defects		Lot 14/Tract 6101	
<div><div></div><div>De Young Properties</div></div>			
Code: ZZ_3154			
Category: Electrical	Location: Master Closet	Description: Light bulb not working in master clpset	Incomplete
Partner: De Young Properties	Type:		
<div><div></div><div>Elia Painting</div></div>			
Code: ZZ_3150			
Category: Paint	Location: Stairwell	Description: Paint touch up needed in stairwell several spots	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_3151			
Category: Paint	Location: Bedroom 1	Description: Paint touch up needed in master bedroom on baseboards	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_3152			
Category: Paint	Location: Bedroom 1	Description: Master bedroom window sill has nail pops and needs caulking Also door trim needs caulking	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_3155			
Category: Paint	Location:	Description: Paint touch up around bull noses and caulk at corners of baseboards	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_3158			
Category: Paint	Location: Entryway	Description: Paint touch up needed next to under stairs storage wall and base board Touch up inside of front door - shell white Bullnose by bed 4 Bullnose inside bed 4	Incomplete
Partner: Elia Painting	Type:		
Code: ZZ_3158			
Category: Paint	Location: Entryway	Description: Paint touch up needed next to under stairs storage wall and base board Touch up inside of front door - shell white Bullnose by bed 4 Bullnose inside bed 4 Gouge in baseboard in bed 4	Incomplete
Partner: Elia Painting	Type:		

All Defects		Lot 14/Tract 6101		
Code: ZZ_3159		Location:	Description: Caulking and paint touch up at baseboards on first floor Corners and base to tile	Incomplete
Category: Paint				
Partner: Elia Painting				
<div><div></div>Matthews Quality Construction</div>				
Code: ZZ_3157		Location: Bedroom 2	Description: Missing door stopper behind closet door for bed 2	Incomplete
Category: Millwork				
Partner: Matthews Quality Construction				
<div><div></div>Ohanians Drywall</div>				
Code: ZZ_3156		Location: Bathroom 2	Description: Drywall line above shower in bath 2	Incomplete
Category: Drywall				
Partner: Ohanians Drywall				
<div><div></div>Tile Interiors</div>				
Code: ZZ_3153		Location: Bathroom 1	Description: Grout cracks at backsplash inn master bath	Incomplete
Category: Tile				
Partner: Tile Interiors				
<div><div></div>Tri Valley Plastering & Drywall</div>				
Code: ZZ_3160		Location: Backyard	Description: Stucco at thresholds in backyard	Incomplete
Category: Stucco				
Partner: Tri Valley Plastering & Drywall				