

All Defects		Lot 133/Tract 0273		
<div><div></div><div>All Phase Construction Clean Up</div></div>				
Code: ZZ_4015				
Category: Clean Up Interior	Location:	Description: Clean house		Incomplete
Partner: All Phase Construction Clean Up	Type:			
<div><div></div><div>Cabinet Connection</div></div>				
Code: ZZ_4001				
Category: Cabinets	Location:	Description: Cabinet scratches in bath 2 on vanity		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4002				
Category: Cabinets	Location:	Description: Cabinet scratches on left vanity in master		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4003				
Category: Cabinets	Location:	Description: Cabinet scratches on right vanity in master bath		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4004				
Category: Cabinets	Location:	Description: Cabinet scratches on center vanity in master bath		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4005				
Category: Cabinets	Location:	Description: Cab scratches on front side of island		Incomplete
Partner: Cabinet Connection	Type:			
Code: ZZ_4006				
Category: Cabinets	Location:	Description: Cabinet scratches around fridge surround		Incomplete
Partner: Cabinet Connection	Type:			

Code: ZZ_4007	Location:	Description: Cabinet scratches to the left of oven on bottom cabinets	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4008	Location:	Description: Cabinet scratches on bottom cabinet right of oven	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4009	Location:	Description: Cab scratches on top cabinets to the left of oven	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4010	Location:	Description: Cabinet scratches to the right of oven top cabinets	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_4019	Location:	Description: Crown is uneven in kitchen	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
<div><div></div>De Young Properties</div>			
Code: ZZ_4020	Location:	Description: Clean garage	Incomplete
Category: Builder Personnel	Type:		
Partner: De Young Properties			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_4014	Location:	Description: Drywall booger in kitchen	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
Code: ZZ_4018	Location:	Description: Drywall by outlet in bed 3	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			
<div><div></div>Westech</div>			

All Defects		Lot 133/Tract 0273		
Code: ZZ_4011				
Category: Electrical	Location:	Description: Missing can lights in master bathroom		Incomplete
Partner: Westech	Type:			
Code: ZZ_4012				
Category: Electrical	Location:	Description: Missing light in master bedroom		Incomplete
Partner: Westech	Type:			
Code: ZZ_4013				
Category: Electrical	Location:	Description: Missing light in great Room		Incomplete
Partner: Westech	Type:			
Code: ZZ_4016				
Category: Electrical	Location:	Description: Missing light in bed 2		Incomplete
Partner: Westech	Type:			
Code: ZZ_4017				
Category: Electrical	Location:	Description: Missing light in bed 3		Incomplete
Partner: Westech	Type:			
Code: ZZ_4021				
Category: Electrical	Location:	Description: Missing carriage light outside man door		Incomplete
Partner: Westech	Type:			