


All Defects		Lot 19/Tract 6100		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_4088		Location:	Description: Missing cabinet door in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4090		Location:	Description: Small chips on corners of 2 drawers in kitchen	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4097		Location:	Description: 2 chips on bottom left drawer on left master vanity Stain coming off on front of cabinet door	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_4098		Location:	Description: Blemish on cabinet door face center vanity of master bath	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>California Building Products</div>				
Code: ZZ_4094		Location:	Description: Finish start up of fireplace	Incomplete
Category: Fireplace Unit		Type:		
Partner: California Building Products				
<div><div></div>Elia Painting</div>				
Code: ZZ_4075		Location:	Description: Nail hole on trim in bed 3	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				
Code: ZZ_4076		Location:	Description: Caulk baseboard in bed 3	Incomplete
Category: Paint		Type:		
Partner: Elia Painting				

Code: ZZ_4077	Location:		
Category: Paint	Type:	Description: Paint marks on door to bed 3	Incomplete
Partner: Elia Painting			
Code: ZZ_4087	Location:		
Category: Paint	Type:	Description: Paint touch up by outlet in kitchen	Incomplete
Partner: Elia Painting			
Code: ZZ_4089	Location:		
Category: Paint	Type:	Description: Excess paint on frame of window in kitchen	Incomplete
Partner: Elia Painting			
Code: ZZ_4093	Location:		
Category: Paint	Type:	Description: Paint touch up on baseboard in kitchen and caulk corners of baseboard	Incomplete
Partner: Elia Painting			
Code: ZZ_4095	Location:		
Category: Paint	Type:	Description: Caulk corner of baseboard in great room and caulk drywall line in corner	Incomplete
Partner: Elia Painting			
Code: ZZ_4096	Location:		
Category: Paint	Type:	Description: Caulk corners of baseboard in master bedroom	Incomplete
Partner: Elia Painting			
Code: ZZ_4100	Location:		
Category: Paint	Type:	Description: Caulk corner of baseboard in master closet	Incomplete
Partner: Elia Painting			
 Ideal Custom Tile			
Code: ZZ_4078	Location:		
Category: Tile	Type:	Description: Grout missing by toilet in bath 2	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_4080	Location:		
Category: Tile	Type:	Description: Grout missing by jambs in bath 2	Incomplete
Partner: Ideal Custom Tile			

Code: ZZ_4081	Location:		
Category: Tile	Type:	Description: Grout missing by jambs in bed 2	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_4085	Location:		
Category: Tile	Type:	Description: Grout missing in several areas in laundry room	Incomplete
Partner: Ideal Custom Tile			
Code: ZZ_4086	Location:		
Category: Tile	Type:	Description: Remove glue off several areas of tile in kitchen	Incomplete
Partner: Ideal Custom Tile			
<div></div> Ohanians Drywall			
Code: ZZ_4074	Location:		
Category: Drywall	Type:	Description: Drywall by outlet in bed 3	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4082	Location:		
Category: Drywall	Type:	Description: Drywall touch up by outlet in hall	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4083	Location:		
Category: Drywall	Type:	Description: Dent on bullnose in hall and line in corner above dent	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4084	Location:		
Category: Drywall	Type:	Description: Drywall patch in hall where hole was cut	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4092	Location:		
Category: Drywall	Type:	Description: Drywall line on wall by kitchen	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_4099	Location:		
Category: Drywall	Type:	Description: Drywall dent in master bathroom	Incomplete
Partner: Ohanians Drywall			

<div><div></div>Quality Plumbing</div>			
Code: ZZ_4091	Location:		
Category: Plumbing	Type:	Description: Plug in and start up water heater	Incomplete
Partner: Quality Plumbing			
<div><div></div>Tri Valley Plastering & Drywall</div>			
Code: ZZ_4101	Location:		
Category: Stucco	Type:	Description: Fog exterior of home where home is splotchy	Incomplete
Partner: Tri Valley Plastering & Drywall			
<div><div></div>Westech</div>			
Code: ZZ_4079	Location:		
Category: Electrical	Type:	Description: Missing globes on vanity light in bath 2	Incomplete
Partner: Westech			