

All Defects		Lot 12/Tract 6180	
<div><div></div>Anlin Windows</div>			
Code: ZZ_128	Location: Dining Room	Description: Screen from slider is missing Screen at Dino room window needs to be popped in Sticker or scratch on the dining room window	Incomplete
Category: Windows	Type: Window frame scratched/chipped/dented		
Partner: Anlin Windows			
Code: ZZ_137	Location:	Description: Missing screen multigen bedroom Slide and glide windows	Incomplete
Category: Windows	Type:		
Partner: Anlin Windows			
<div><div></div>Cabinet Connection</div>			
Code: ZZ_129	Location: Kitchen	Description: Chip in cabinet under sink in kitchen Kitchen base trim missing Various chips on kitchen cabinets - see blue tape Couple doors missing hardware	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_133	Location: Multi-Gen Kitchenette	Description: Various scratches in multi-gen kitchen cabinets	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_146	Location:	Description: Master bath vanity cabinets need adjusmtm	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_148	Location: Bedroom 1	Description: Master closet cabinets various scratches	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
<div><div></div>Citadel Roofing and Solar</div>			

Code: ZZ_136			
Category: Roofing	Location: Bedroom 3	Description: Cracked roof tile just. Outside of bedroom 3	Incomplete
Partner: Citadel Roofing and Solar	Type:		
<div><div></div>De Young Properties</div>			
Code: ZZ_139			
Category: Plumbing	Location: Bathroom 3	Description: bath 3 various rust stains in bathtum	Incomplete
Partner: De Young Properties	Type:		
Code: ZZ_143			
Category: Paint	Location: Bedroom 2	Description: Bed 2 paint touch up at bull nose at entry top and bottom	Incomplete
Partner: De Young Properties	Type:		
<div><div></div>Everlast Paint</div>			
Code: ZZ_134			
Category: Paint	Location: Bathroom 4	Description: Closet in downstairs bedroom The mill work needs toucp	Incomplete
Partner: Everlast Paint	Type:		
Code: ZZ_142			
Category: Paint	Location:	Description: various cabinet scratches in bathroom 2	Incomplete
Partner: Everlast Paint	Type:		
<div><div></div>HSI</div>			
Code: ZZ_135			
Category: Fire Sprinklers	Location: Multi-Gen Bathroom	Description: Missing fire sprinkler cap in multigen bathroom	Incomplete
Partner: HSI	Type:		
<div><div></div>John Ventresca Co</div>			

All Defects		Lot 12/Tract 6180	
Code: ZZ_131			
Category: Fireplace Surround	Location: Great Room	Description: Fireplace surround needs repair Various stains and grout touch up on top left corner	Incomplete
Partner: John Ventresca Co	Type:		
<div><div></div> Ohanians Drywall</div>			
Code: ZZ_138			
Category: Drywall	Location: Bedroom 3	Description: Drywall touch up bedroom 3 window sill	Incomplete
Partner: Ohanians Drywall	Type:		
Code: ZZ_141			
Category: Drywall	Location: Bathroom 2	Description: Bath 2 next to outlet needs touch up	Incomplete
Partner: Ohanians Drywall	Type:		
Code: ZZ_145			
Category: Drywall	Location:	Description: Touch up dry wall at window sill in master bathroom	Incomplete
Partner: Ohanians Drywall	Type:		
Code: ZZ_149			
Category: Drywall	Location: Bathroom 1	Description: Drywall touch up in corner of master bathroom next to closet and near shower tile transition	Incomplete
Partner: Ohanians Drywall	Type:		
<div><div></div> Quality Plumbing</div>			
Code: ZZ_132			
Category: Plumbing	Location: Multi-Gen Bathroom	Description: Multigen toilet The top cover for bolts at base of toilet are not staying on	Incomplete
Partner: Quality Plumbing	Type:		
Code: ZZ_140			
Category: Plumbing	Location: Bathroom 2	Description: Bath 2 toilet seat chip	Incomplete
Partner: Quality Plumbing	Type:		

All Defects		Lot 12/Tract 6180				
Code: ZZ_150						
Category: Plumbing	Location: Side Yard		Description: Condensation line missing elbow on side of house	Incomplete		
Partner: Quality Plumbing	Type:					
<div><div></div> Simas Flooring & Design</div>						
Code: ZZ_130						
Category: Carpet / Hardwood / Laminate	Location: Kitchen		Description: Perimeter seal missing in Kitchen	Incomplete		
Partner: Simas Flooring & Design	Type:					
<div><div></div> Tile Interiors</div>						
Code: ZZ_147						
Category: Tile	Location: Bathroom 1		Description: Grout touch up in master bath Nest to master tub Next to shower and drywall is really bad Grout mud droplets on floor	Incomplete		
Partner: Tile Interiors	Type:					
<div><div></div> Tri Valley Plastering & Drywall</div>						
Code: ZZ_127						
Category: Stucco	Location: Entryway		Description: Please touch up stucco at bottom of entry	Incomplete		
Partner: Tri Valley Plastering & Drywall	Type: Stained stucco					
Code: ZZ_144						
Category: Stucco	Location: Entryway				Description: White substance at footing outside of emtry	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:					