

All Defects		Lot 28/Tract 6260	
<div><div></div>Anlin Windows</div>			
Code: ZZ_233	Location: Entryway	Description: Both operable windows in hallway by courtyard needs screens and dont lock	Incomplete
Category: Windows	Type:		
Partner: Anlin Windows			
Code: ZZ_237	Location: Den	Description: Left window in den doesn't lock Right window needs slide and glide	Incomplete
Category: Windows	Type: Window operation		
Partner: Anlin Windows			
<div><div></div>Cabinet Connection</div>			
Code: ZZ_222	Location: Bathroom 2	Description: Bath 2 right side cabinet drawer and door need adjustment Various scratches on the outside and inside of the cabinets on vanity Toe kick missing from bath 2	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
Code: ZZ_240	Location: Bathroom 1	Description: Master bathroom cabinets have various chips and scratches Please adjust doors in middle of vanity Check all drawer alignment	Incomplete
Category: Cabinets	Type: Dent(s), ding(s), scratch(es)		
Partner: Cabinet Connection			
<div><div></div>Central Valley Rain Gutters</div>			
Code: ZZ_243	Location: Front Yard	Description: Missing gutter down spout or drain missing cap?	Incomplete
Category: Rain Gutters	Type:		
Partner: Central Valley Rain Gutters			
<div><div></div>Everlast Paint</div>			
Code: ZZ_219	Location: Bedroom 4	Description: No caulking at window frame Paint touch up needed around window	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			

All Defects		Lot 28/Tract 6260	
Code: ZZ_221			
Category: Paint	Location: Bedroom 4	Description: Paint touch up needed in various places in bedroom 4	Incomplete
Partner: Everlast Paint	Type: Cleanup		
Code: ZZ_223			
Category: Paint	Location: Bathroom 2	Description: Caulking and paint touch up needed at bath tub and near sink in bathroom 2	Incomplete
Partner: Everlast Paint	Type: Cleanup		
Code: ZZ_224			
Category: Paint	Location: Bedroom 3	Description: Bed 3 caulking and paint touch up at window frame	Incomplete
Partner: Everlast Paint	Type: Cleanup		
Code: ZZ_225			
Category: Paint	Location: Bedroom 2	Description: Bed 3 - Caulking and paint touch up behind door at the baseboard	Incomplete
Partner: Everlast Paint	Type: Cleanup	Various paint touch-up	
Code: ZZ_227			
Category: Paint	Location: Bedroom 2	Description: Caulking and Paint touch up needed around the windows in bedroom 2	Incomplete
Partner: Everlast Paint	Type: Cleanup		
Code: ZZ_228			
Category: Paint	Location: Bedroom 2	Description: Various paint touch up needed in bedroom 2	Incomplete
Partner: Everlast Paint	Type: Cleanup		
Code: ZZ_231			
Category: Paint	Location: Laundry Room	Description: Paint touch up needed in laundry room various spots	Incomplete
Partner: Everlast Paint	Type: Cleanup		
Code: ZZ_232			
Category: Paint	Location: Entryway	Description: Caulking and touch up needed at hallways windows next to courtyard	Incomplete
Partner: Everlast Paint	Type:		
Code: ZZ_234			
Category: Paint	Location: Great Room	Description: Paint touch up and caulking at slider to courtyard and slider to backyard	Incomplete
Partner: Everlast Paint	Type: Cleanup	Neither frames painted	

All Defects

Lot 28/Tract 6260

Code: ZZ_236	Location: Den	Description: Paint touch up and caulking needed at windows to the courtyard from the den - both windoes	Incomplete
Category: Paint	Type: Cleanup		
Partner: Everlast Paint			
Code: ZZ_238	Location: Den	Description: Paint touch up needed in den	Incomplete
Category: Paint	Type: Cleanup		
Partner: Everlast Paint			
Code: ZZ_239	Location: Den	Description: Dry wall and paint touch up needed next to den entry door - next to frame	Incomplete
Category: Paint	Type: Cleanup		
Partner: Everlast Paint			
Code: ZZ_242	Location: Bathroom 1	Description: Paint touch up throughout master bath and in master closet And caulking needed in baseboards in master closet	Incomplete
Category: Paint	Type:		
Partner: Everlast Paint			
<div><div></div>John Ventresca Co</div>			
Code: ZZ_235	Location: Great Room	Description: Fireplace surround has various cracks that need to be filled	Incomplete
Category: Fireplace Surround	Type:		
Partner: John Ventresca Co			
<div><div></div>Matthews Quality Construction</div>			
Code: ZZ_220	Location:	Description: Adjust closet door - bedroom 4	Incomplete
Category: Millwork	Type:		
Partner: Matthews Quality Construction			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_226	Location: Bedroom 2	Description: Bed 2 dry wall texture by window	Incomplete
Category: Drywall	Type:		
Partner: Ohanians Drywall			

All Defects		Lot 28/Tract 6260		
Code: ZZ_229				
Category: Drywall	Location: Bedroom 2	Description: Dry wall touch up on wall to the left of the window in bedroom 2	Incomplete	
Partner: Ohanians Drywall	Type:			
Code: ZZ_230				
Category: Drywall	Location: Laundry Room	Description: Drywall texture issue in laundry room on wall behind doors 3 places	Incomplete	
Partner: Ohanians Drywall	Type:			
Code: ZZ_241				
Category: Drywall	Location: Bathroom 1	Description: Dry wall texture next to right side vanity	Incomplete	
Partner: Ohanians Drywall	Type: Crack/gash/ding			
<div><div></div>True Frame</div>				
Code: ZZ_244				
Category: Framing	Location: Garage	Description: Cracked and separating fascia board above the garage	Incomplete	
Partner: True Frame	Type:			
Code: ZZ_244				
Category: Framing	Location: Garage	Description: Cracked and separating fascia board above the garage	Incomplete	
Partner: True Frame	Type:			