




All Defects		Lot 10/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_3661	Location:	Description: Screen torn in dining room	Incomplete	
Category: Windows	Type:			
Partner: Anlin Windows				
Code: ZZ_3662	Location:	Description: Window latch not working in great room	Incomplete	
Category: Windows	Type:			
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_3656	Location:	Description: Install under strip for upper cabinets to cover under cabinet outlet	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3657	Location:	Description: Scribe missing either side of island	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3658	Location:	Description: Install 1/4 round in kitchen by laminate	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3659	Location:	Description: Crown crooked on left side on fridge surround	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3660	Location:	Description: Touch up on filler collems around fridge	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				
Code: ZZ_3674	Location:	Description: Pencil mark on top of cabinet in bath 2 small vanity	Incomplete	
Category: Cabinets	Type:			
Partner: Cabinet Connection				

All Defects		Lot 10/Tract 6164		
Code: ZZ_3678		Location: Type:	Description: 1/2 round cabinet trim missing in master bath	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
Code: ZZ_3680		Location: Type:	Description: Trim touch up on cabinets in master closet	Incomplete
Category: Cabinets				
Partner: Cabinet Connection				
<div><div></div>California Building Products</div>				
Code: ZZ_3654		Location: Type:	Description: Start up fireplace	Incomplete
Category: Fireplace Unit				
Partner: California Building Products				
<div><div></div>De Young Properties</div>				
Code: ZZ_3663		Location: Type:	Description: Paint touch up in super bonus room wall	Incomplete
Category: Paint				
Partner: De Young Properties				
Code: ZZ_3664		Location: Type:	Description: Paint touch up in entry way where drywall repair was made	Incomplete
Category: Paint				
Partner: De Young Properties				
Code: ZZ_3666		Location: Type:	Description: Paint touch up on bullnose by garage door	Incomplete
Category: Paint				
Partner: De Young Properties				
Code: ZZ_3667		Location: Type:	Description: Paint touch up by window and wall in bed 4	Incomplete
Category: Paint				
Partner: De Young Properties				
Code: ZZ_3669		Location: Type:	Description: Paint touch up behind toilet in bath 3	Incomplete
Category: Paint				
Partner: De Young Properties				


Code: ZZ_3670	Location:	Description: Paint touch up in stairwell where drywall touch up was done	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3671	Location:	Description: Paint touch up where drywall repair was made on upstairs landing	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3672	Location:	Description: Paint touch up on wall in bed 3	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3673	Location:	Description: Paint touch up in upstairs hall by bed 3	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3677	Location:	Description: Paint touch up in master bed by windows	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3679	Location:	Description: Paint touch up on pony wall by master shower	Incomplete
Category: Paint	Type:		
Partner: De Young Properties			
Code: ZZ_3681	Location:	Description: Hose off back patio	Incomplete
Category: Builder Personnel	Type:		
Partner: De Young Properties			
 Elia Painting			
Code: ZZ_3668	Location:	Description: Paint drip on cabinet in bath 3	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
 Ferguson			

Code: ZZ_3653	Location:		
Category: Appliances	Type:	Description: Missing microwave	Incomplete
Partner: Ferguson			


 Ideal Custom Tile

Code: ZZ_3675	Location:		
Category: Tile	Type:	Description: 3 scratches subway tiles in bath 2	Incomplete
Partner: Ideal Custom Tile			


Code: ZZ_3676	Location:		
Category: Tile	Type:	Description: Missing tile toe kick in bath 2	Incomplete
Partner: Ideal Custom Tile			

 John Ventresca Co

Code: ZZ_3655	Location:		
Category: Fireplace Surround	Type:	Description: Grout cracks around fireplace insert	Incomplete
Partner: John Ventresca Co			

 Matthews Quality Construction

Code: ZZ_3665	Location:		
Category: Millwork	Type:	Description: Door to garage will not auto close	Incomplete
Partner: Matthews Quality Construction			

 Quality Plumbing

Code: ZZ_3685	Location:		
Category: Plumbing	Type:	Description: Cut drain pipe for upstairs laundry room on back patio	Incomplete
Partner: Quality Plumbing			

 Tri Valley Plastering & Drywall

All Defects		Lot 10/Tract 6164		
Code: ZZ_3683				
Category: Stucco		Location:	Description: Stucco crack right side of home	Incomplete
Partner: Tri Valley Plastering & Drywall		Type:		
Code: ZZ_3684				
Category: Stucco		Location:	Description: Stucco fog and repair back left side of home	Incomplete
Partner: Tri Valley Plastering & Drywall		Type:		
<div><div></div>Westech</div>				
Code: ZZ_3682				
Category: Electrical		Location:	Description: Finish exterior electrical panel	Incomplete
Partner: Westech		Type:		