

All Defects		Lot 19/Tract 6260		
<div><div></div>Cabinet Connection</div>				
Code: ZZ_1140		Location:	Description: Scratch on drawer right side of oven	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1141		Location:	Description: Scratch on drawer left side of oven	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1143		Location:	Description: Missing handle on drawer above dwb	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_1148		Location:	Description: Scratch on drawer in master bath	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
<div><div></div>De Young Properties</div>				
Code: ZZ_1132		Location:	Description: Rust at bottom of tub in bath 2	Incomplete
Category: Builder Personnel		Type:		
Partner: De Young Properties				
<div><div></div>Everlast Paint</div>				
Code: ZZ_1134		Location:	Description: Paint inside of closet door in bed 3	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				
Code: ZZ_1136		Location:	Description: Paint behind front door	Incomplete
Category: Paint		Type:		
Partner: Everlast Paint				

All Defects

Lot 19/Tract 6260

Code: ZZ_1138	Location:		
Category: Paint	Type:	Description: Caulk baseboard in hall by entry	Incomplete
Partner: Everlast Paint			
Code: ZZ_1139	Location:		
Category: Paint	Type:	Description: Caulk baseboard by kitchen	Incomplete
Partner: Everlast Paint			
Code: ZZ_1142	Location:		
Category: Paint	Type:	Description: Paint on cabinet door and paint on cabinet handle	Incomplete
Partner: Everlast Paint			
Code: ZZ_1144	Location:		
Category: Paint	Type:	Description: Paint wall by dining room	Incomplete
Partner: Everlast Paint			
Code: ZZ_1145	Location:		
Category: Paint	Type:	Description: Paint corners of crown in dining room	Incomplete
Partner: Everlast Paint			
Code: ZZ_1146	Location:		
Category: Paint	Type:	Description: Paint crown and ceiling in great room	Incomplete
Partner: Everlast Paint			
Code: ZZ_1149	Location:		
Category: Paint	Type:	Description: Caulk baseboard in great room area	Incomplete
Partner: Everlast Paint			

Tile Interiors

Code: ZZ_1133	Location:		
Category: Tile	Type:	Description: Grout cracks on either side of tub in bath 2	Incomplete
Partner: Tile Interiors			
Code: ZZ_1135	Location:		
Category: Tile	Type:	Description: Grout in hall by bed 3	Incomplete
Partner: Tile Interiors			

All Defects		Lot 19/Tract 6260		
Code: ZZ_1137		Location:  Type:	Description: Grout by entry way by baseboard	Incomplete
Category: Tile				
Partner: Tile Interiors				
Code: ZZ_1147		Location:  Type:	Description: Clean thunder off shower in master bath	Incomplete
Category: Tile				
Partner: Tile Interiors				
<div><div></div>Tri Valley Plastering &amp; Drywall</div>				
Code: ZZ_1150		Location:  Type:	Description: Fog by back window under weep screed	Incomplete
Category: Stucco				
Partner: Tri Valley Plastering & Drywall				