



**DO NOT CONNECT GALVANOMETER
ACROSS BATTERY**

Needle moves to the right:
Indicates positive conventional
current flowing into the + terminal.

Needle moves to the left:
Indicates positive current flowing
out of the + terminal.