


## Detection Report


Fender ID	Defect ID	Timestamp	Class	Confidence	Bounding Box	Frame Number
1	1	3.233	Missing plate	0.599	(1091.771, 598.786, 1187.942, 874.432)	97

Cropped Image




Fender ID	Defect ID	Timestamp	Class	Confidence	Bounding Box	Frame Number
1	2	6.833	Missing plate	0.27	(1073.213, 337.165, 1115.99, 483.438)	205

Cropped Image



Fender ID	Defect ID	Timestamp	Class	Confidence	Bounding Box	Frame Number
1	3	7.0	Loose plate	0.255	(1047.939, 289.87, 1094.46, 399.043)	211

Cropped Image



Fender ID	Defect ID	Timestamp	Class	Confidence	Bounding Box	Frame Number
1	4	7.467	Missing plate	0.264	(1102.574, 442.43, 1150.099, 613.725)	225



Cropped Image



Fender ID	Defect ID	Timestamp	Class	Confidence	Bounding Box	Frame Number
1	5	7.667	Missing plate	0.254	(1114.5, 485.426, 1167.469, 667.938)	231

Cropped Image



Fender ID	Defect ID	Timestamp	Class	Confidence	Bounding Box	Frame Number
1	6	7.967	Missing plate	0.263	(1130.006, 552.129, 1194.09, 760.207)	240

Cropped Image



Fender ID	Defect ID	Timestamp	Class	Confidence	Bounding Box	Frame Number
1	7	8.833	Missing plate	0.386	(1225.257, 869.698, 1321.212, 1072.354)	265

Cropped Image

