

First County Scaffolding

Report prepared for
Carillion

SCAFFOLD
INSPECTION REPORT

Site

CADS Offices, Arrowsmith Court, 10 Station Approach, Broadstone, Dorset, BH188AX

Inspector

John Smith

Date

5th August 2016

Score

91%

Table Of Contents

INSPECTION SUMMARY

Overall: 91%	3
Plot One: 80%	3
Plot Two: 90%	3


DETAILED REPORT

Foundations	4
Bracing	4
Transoms	4

APPENDIX

Inspection Summary

91%
Overall Score



Plot One: 80%

00001	Reception Area, Narrow Gable, North Elevation	100%
00002	Reception Area, Narrow Gable, North Elevation	100%
00003	Reception Area, Narrow Gable, North Elevation	100%
00004	Reception Area, Narrow Gable, North Elevation	100%
00005	Reception Area, Narrow Gable, North Elevation	100%

Detailed Report

Foundations

- Adequate sole boards for ground conditions.
- Adequate sole boards for ground conditions.
- Correct use of base plates.
- Foot ties installed if applicable.
- Foot ties installed if applicable.



Bracing

- Facade bracing every 6 bays.



00003 - Roof level void zone 1 (appendix 1)

Facade bracing has been removed from one of the bays due to third party interference.

- Adequate sole boards for ground conditions.
- Correct use of base plates.
- Foot ties installed if applicable.
- Foot ties installed if applicable.





Appendix

Appendix 1

Appendix 2

Appendix 3

Appendix 4



Appendix 5

Appendix 6

Appendix 7

Appendix 8

