

ENERVA

Energy Solutions Inc.

ENERGY AUDIT REPORT

Pre-Retrofit Assessment

Report Details

Audit ID: e400af71-27b3-4a51-8bb5-b0a9130f174c
Report Date: 2025-06-10
Audit Date: 2025-06-09

Customer Information

Name: Tarun Test
Email: test@test.ca
Phone: 4038709512
Address: Test
Location: Calgary, AB, A1A1A1

Property Details

Home Type: Attached
Audit Type: Pre-Retrofit Assessment

House Information		Foundation Information	
House Type: bungalow		Type: basement	
Year Built: 2019		Wall Height: Not specified	
Height: 22.50 ft		Walls: Not specified	
Orientation: NW		Insulation: Not specified	
Walls Information		Ceiling Information	
Wall Framing: 2x6		Attic Framing: 2x6	
Centers: 488		Insulation Type: glass	
Cavity Insulation: None		Insulation Not specified	
Exterior Finish: stucco		Ceiling Type: cathedral	
Windows Information		Doors Information	
Frame Material: aluminum		Skin Material: wood	
Low-E Coating: yes		Insulation: eps	
Gas Fill: yes			
Glazing: 2			
Heating System		Domestic Hot Water	
System Type: embo, csa_p9_11		System Type: induced_direct_vent	
Fuel Source: propane		Fuel Type: propane	
Manufacturer: Test Man Heat		Manufacturer: Test manu DHW	
Model: Test		Tank Volume:	
Ventilation System		Renewable Systems	
Ventilation Type: forced		Solar PV Present:	
HRV Manufacturer: Test		Solar DHW: Test DHW	
HRV Model: Test			
HVI Certified: no			
Test Results			
<div>Blower Door Test</div> <div>Areas of Leakage:</div> <div><ul style="list-style-type: none">RimsBaseboardsCeiling Fixtures</div> <div>Other: Test</div> <div>Depressurization Test</div>			
Audit Photos			

Photo could not be loaded: 2.4.png

Photo could not be loaded: 2.1 (1).png

Photo could not be loaded: 2.1 (5).png

Photo could not be loaded: 2.1 (8).png

Photo could not be loaded: 2.1 (7).png

Photo could not be loaded: 2.1 (6).png

Photo could not be loaded: 2.1 (5).png

Photo could not be loaded: 2.1 (4).png

Photo could not be loaded: WhatsApp Image 2025-06-09 at 8.35.50 AM.jpeg