


### Does this solve the problem?

- **Explanation**  
**IN THE AT2 CABINET:**



Relevant spare parts	
Description	Item No.
CABLE Y-JZ 8G0.75mm2 IEC	<a href="#">60008948</a>
CRP TERM 0.75 8MM INS SINGLE	<a href="#">60006336</a>

**Check and replace the TAC-II, if it is found defective**

### Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

Check the TAC-II relevant input signal and replace the TAC-II, if it's not working as intended with available

signal/voltage

Relevant spare parts	
Description	Item No.
TAC-II/F NEGM NM1500C/72/82	<a href="#">51707301</a>