

## Check and replace the TOI II

Does this solve the problem?


1] Yes

2] No

3] I don't know

- **Explanation**

Check the Gear Oil Pressure transducer, connector and cable condition.



Relevant spare parts

Description	Item No.
CABLE -W537 NM30T MODUL 2x1	60103096
TOI-II INTERF EXT POC	<a href="#">51701601</a>