
May 3, 2023

To: Alex Granados, Angel Cruz, Jesus Zelaya, Ryan Beery, Edie Stinnette, John Paul, Erick Shaffer

From: Jesus Zelaya

This report is a follow up to the safety inspection completed on May 3, 2023. The purpose of the inspection was to identify potential safety hazards and/or OSHA violations.

Attached is a list of observations and recommendations based on the conditions present at the time of my visit. Please review the report and verify that all potential hazards are corrected.

If you have any questions or require additional information after reviewing this report, please don't hesitate to contact me.

Sincerely,

Jesus Zelaya
LF Jennings, Inc.
Safety Department
(703) 336-2023
jesus.zelaya@lfjennings.net



05/03/2023

Project Safety Inspection

FAIRFAX CORNER

Reported by: Jesus Zelaya

On-site Supervisor: Erick Shaffer

Scope of inspection:

Observation 1

Missing parts

Level 1 we found this scaffold that was missing outrigger which is not safe to work like that . We talk to painters they did the correction.



Observation 2

Precautions

Ground level this door needs to be closed because there is a swing stage above or we can place a over head protection



Observation 3

Preventions

Parking garage they are doing coat in the floor they have closed doors to prevent people slip or trip



Observation 4

Precautions

Ground level they are working in a main Hole for good prevention they have confined space tripod installed which is a safe operation



Observation 5

Personal protective equipment

Level 4 we found some guys working in court yard with not hard hat on . We talked to them they did the correction



Observation 6

Fire protection

Level 7 fire extinguishers are there in the middle of walkway ready to be use in case of fire





Submitted by:
Jesus Zelaya

L.F. Jennings.
Safety Department
(703) 336-2023
jesus.zelaya@lfjennings.net



05/03/2023

Project Safety Inspection

FAIRFAX CORNER

Reported by: Jesus Zelaya

On-site Supervisor: Erick Shaffer

Scope of inspection:

Observation 1

Missing parts

Level 1 we found this scaffold that was missing outrigger which is not safe to work like that . We talk to painters they did the correction.

Observation 2

Precautions

Ground level this door needs to be closed because there is a swing stage above or we can place a over head protection

Observation 3

Preventions

Parking garage they are doing coat in the floor they have closed doors to prevent people slip or trip

Observation 4

Precautions

Ground level they are working in a main Hole for good prevention they have confined space tripod installed which is a safe operation

Observation 5

Personal protective equipment

Level 4 we found some guys working in court yard with not hard hat on . We talked to them they did the correction

Observation 6

Fire protection

Level 7 fire extinguishers are there in the middle of walkway ready to be use in case of fire