



SERVICE BULLETIN

BULLETIN: 2020-06-16 VFPA Liner/Burner Fix Kit

ISSUED: 2020-07-08

MODELS:

32 Inch Units	36 Inch Units
VFPA32BP30LP	VFPA36BP30LP
VFPA32BP30LN	VFPA36BP30LN
VFPA32BP31LP	VFPA36BP31LP
VFPA32BP31LN	VFPA36BP31LN
VFPA32BP70LP	VFPA36BP70LP
VFPA32BP70LN	VFPA36BP70LN
VFPA32BP71LP	VFPA36BP71LP
VFPA32BP71LN	VFPA36BP71LN

SUBJECT: VFPA Fireplaces were built with an incorrect log shelf which is part of the burner assembly. This causes the fiber liner accessory not to fit.

SOLUTION: Instructions (42016) are available and attached here to cut down the rear fiber liner to fix this issue in the field; you may also choose to have the whole burner assembly returned. Please contact technical support for further details.