


24H3-211C


Single Curb



Structure Summary

Facility ID	24H3-211C
Maximo Asset ID	GIS-1109789
MSD Service Area	Sulphur (Area 1)
Ownership	MSD
Status	Active

Pipe	Clock	Flow	Connection
1	6	Out	24H3-205C



General Information

System	Combined
Data Layer	sslInlet
Subtype	Single
Original InletType	<Null>
Inlet Type	Curb
Date	October 10, 2024
Weather	Dry
Diving Structure?	No
Report Asset Integrity Issue?	No

Location

Address	4976 Blow St, Saint Louis, St. Louis city, Missouri 63109, USA
Manually Update Address?	No
Location Code	(B) Secondary Roads
Surface Type	(A) Asphalt, (D) Grass/Dirt

Area Photo (Post-Inspection)



Topside Photo



Wall Material	Brick
----------------------	-------

Additional Location Photos

Pipe Connections (1 Item)

Pipe Connections - 1. 6, Out, (XXX) Not Known, 24H3-205C

MSD pipe facility ID	24H3-211C:24H3-205C
Pipe System	C
Pipe Number	1
Can you verify pipe characteristics?	No
Reason Cannot Verify	BULKHEAD PRESENT
Trench Grate Y/N	No
Pipe Status	Active
Clock Position	6
Pipe Direction	Out
Pipe Type	(GR) Gravity Connection
Pipe Material	(XXX) Not Known
Rehab Type	NONE
Connecting Structure ID	24H3-205C

Pipe Photo - Report



Additional Pipe Photos