



SERVICE BULLETIN 235
ISSUED: 09/24/2025

Mandatory Inspection and Fix of Engine Harness Adapter on SVRII-36A-23BV

SUBJECT: Inspect and fix or replace engine harness adapter on certain serial numbers of SVRII-36A-23BV.

SITUATION: It has come to our attention that the engine harness adapter may not be wired correctly. This may result in the unit not shutting off properly.

SOLUTION: To ensure optimal performance and customer satisfaction we advise that all units within the serial number range below be inspected and either have the engine harness rewired or replaced. Confirm fix shutting off by engine with all combinations of interlock functions. Refer to Operator's Manual for details.

UNITS

AFFECTED:

Model
SVRII-36A-23BV

Serial Number
W7800155 - W7800202

REQUIRED: 487609 Harness Adapter

WARRANTY: Use Failure Code X4-175
.50 hrs labor

