


Navigation and toolbars with icons for file operations, editing, and simulation.

Operations Manager

Solids

Machine Group-1
Properties - Mill Default MM
Toolpath Group-1
1 - Facing - [WCS: TOP] - [Tplane: TOP]
Parameters
#2 - M40.00 FACE MILL -
Geometry - (1) chamf6
Toolpath - 25.X - 22MEB0A24_EXP_8
2 - Drill/Counterbore - [WCS: TOP] - [Tplane: TOP]
Parameters
#3 - M5.00 DRILL -
Geometry - (5) Points
Toolpath - 5.X - 22MEB0A24_EXP_8
3 - Drill/Counterbore - [WCS: TOP] - [Tplane: TOP]
Parameters
#4 - M10.00 DRILL -
Geometry - (4) Points
Toolpath - 5.0K - 22MEB0A24_EXP_8
4 - Circle Mill - [WCS: TOP] - [Tplane: TOP]
Parameters
#6 - M10.00 ENDMILL FLAT -
Geometry - (1) Points
Toolpath - 11.X - 22MEB0A24_EXP_8



Verify dialog box with various controls and settings.

Verify

Display control

Moves/step: 1

Moves/refresh: 1

Speed: 100%

Quality: 100%

Update after each toolpath

Stop options

☐ Stop on collision

☐ Stop on tool change

☐ Stop after each operation

Verbose

Operation #: 4

Toolpath: Circle Mill

Tool #: 6

Tool label:

100%

118.87027 X 65.48022 Y 0.0 Z

ALL Only... In


Ribbon Bar

Operations Manager

Toolpaths Solids

Machine Group-1

- Properties - Mill Default.MM
- Toolpath Group-1
 - 1 - Facing - [WCS: TOP] - [TPlane: TOP]
 - Parameters
 - 2 - M40.00 FACE MILL - Geometry - (1) cham(s)
 - Toolpath - 25.7K - 22MEB0A24_EXP_8
 - 3 - Drill/Counterbore - [WCS: TOP] - [TPlane: TOP]
 - Parameters
 - Geometry - (5) Points
 - Toolpath - 5.5K - 22MEB0A24_EXP_8
 - 4 - M10.00 DRILL - Geometry - (4) Points
 - Toolpath - 5.0K - 22MEB0A24_EXP_8
 - 5 - Circle Mill - [WCS: TOP] - [TPlane: TOP]
 - Parameters
 - Geometry - (1) Points
 - Toolpath - 11.2K - 22MEB0A24_EXP_8



View:ISO WCS:TOP TPlane:TOP

For help, press Alt+H.

Thunderstorm w...
In effect

Search

3D Gview Planes Z 0.0 10 Level 1 Attributes # WCS Groups

ENG IN 07:20 07-10-2025